

MCCARTHY (15Z)(PAMX) 1 NE UTC-9(-8DT) N61°26.27' W142°054.15'

1533 NOTAM FILE MXY

RWY 01-19: 3501X60 (GRVL-DIRT) 0.3% up S

RWY 01: Brush.

RWY 19: Brush.

AIRPORT REMARKS: Unattended. Rwy cond unmet; rcmd visual insp prior to Indg. Wildlife invof rwy. Rwy 01 apch ovr old McCarthy Arpt.

AIRPORT MANAGER: 907-822-3222

COMMUNICATIONS: CTAF 122.9

RADIO AIDS TO NAVIGATION: NOTAM FILE GKN.


GULKANA (H) (H) VOR/DME 115.6 GKN Chan 103 N62°09.23'

W145°26.84' 103° 84.3 NM to fld. 1549/17E.

COMM/NAV/WEATHER REMARKS: For a toll free call to Kenai FSS dial 1-866-864-1737.

ANCHORAGE

L-1A, 3E



SWIFT CREEK (AK31) PVT 3 SW UTC-9(-8DT) N61°24.67' W143°00.07'

ANCHORAGE

1225 NOTAM FILE Not insp.

RWY 16-34: 2000X35 (TURF)

RWY 16: Trees.

RWY 34: Trees.

AIRPORT REMARKS: Unattended. Creek and sharp ditches close to rwy S approximately 1/2 mile.

AIRPORT MANAGER: 907-521-0178

COMM/NAV/WEATHER REMARKS: For a toll free call to Kenai FSS dial 1-866-864-1737.

MCKINLEY PARK

DENALI (AK06) PVT 4 SW UTC-9(-8DT) N63°38.42' W148°47.52'

ANCHORAGE

H-1B, 2K, L-3D

2050 NOTAM FILE FAI

RWY 12-30: 4000X50 (GRVL)

RWY 12: Trees. Rgt tfc.

AIRPORT REMARKS: Unattended. CLOSED to the public. All tfc patterns to the West. Windy pass tfc should be alert for high volume of tfc from May 15 to Sep 15. Phone is primary contact method. Email for auxiliary contact.

AIRPORT MANAGER: 907-748-2800

RADIO AIDS TO NAVIGATION: NOTAM FILE ENN.

NENANA (H) (H) VORTAC 115.8 ENN Chan 105 N64°35.40'

W149°04.37' 152° 57.6 NM to fld. 1601/21E.

VOR unusable:

086°-096° byd 34 NM blo 5,000'

097°-105°

310°-335° byd 33 NM blo 5,000'

336°-360° byd 33 NM blo 4,000'

TAC AZM unusable:

097°-105°

DME unusable:

097°-105°

COMM/NAV/WEATHER REMARKS: For a toll free call to Fairbanks FSS dial 1-866-248-6516.

