

EARECKSON AS (SYA)(PASY) AF O S UTC-10(-9DT) N52°42.74' E174°06.82'

W ALEUTIAN ISLS

98 B NOTAM FILE PASY Not insp.

H-2H, L-2H

RWY 10-28: H10004X150 (ASPH-GRVD) PCN 38 F/A/W/T HIRL

DIAP, AD

RWY 10: ALSF1. PAPI(P4L)—GA 2.5° TCH 45'. Rgt tfc.

RWY 28: SALSF. PAPI(P4L)—GA 2.5° TCH 49'.

ARRESTING GEAR/SYSTEM

RWY 10 MB100 (B) 1850 FT UNUSBL.

BAK12(B) 4450 FT. **RWY 28**

SERVICE: LGT Arpt has rgrl & LED obstn lgt; LED lgt may not be vsb to ngt vision devices. ACTVT ALSF1 Rwy 10; SALSF Rwy 28, HIRL Rwy 10-28—CTAF. PAPI Rwy 10 and Rwy 28 opr consly.

MILITARY REMARKS: Attended Mon-Fri 1800-0300Z† (0800-1700 local), clsd wkend and hol. USAF installation; clsd to civ ops. Mil/civ declared emerg & in distress will be honored. RCR/RSC same as atndd hr. FICON and rwy cond code not rptd. ARFF Index 7C. 7 day site arr or 45 day foreign natnl req—D317-552-5020/5107/C907-552-5020/5107 and PPR—D317-392-3505/3606/4005/C907-392-3505/3606/4005. Svc fee rqrd. Tran svc Mon-Fri 1800-0300Z†; clsd wkend and hol. Aft hr may incur O/T and svc fee. Mandatory and info signs not installed. Hvy goose actvt Apr-Jun and Aug-Oct; Gulls & ravens invof arpt. Rpt bird/wildlife strikes on or invof Eareckson—EAS Afld Ops/twr D317-392-3505/C907-392-3505 & 3WG/SEF & USDA-WS D317-552-4798/4128 or C907-552-4798/4128. Flts originating outside the United States refer to AK section of USAF—Foreign Clnc Guide. 30 min PN for barrier svc.

C-130/L-100 wt rstrd max 137 kps arr or dep via Twy B; gtr than 137 kips use Twy C and M. **CAUTION:** Illusion of hgt & usbl rwy wid psbl lngd durg low vsby & at ngt. Non std VFR pat Rwy 10. Twy A, D and pri HCP clsd. Alt HCP 72 hr PPR. Hills 8 NM west 662' MSL. Rwy 10-28 with 25' shoulders. **CAUTION:** Rwy 10-28 200' turn radius max; tow bar and psnl for lrg coml acft rqr gtr than 200' turnaround NA. No overrun; sheer drop offs. Coord ETOP or afld criteria—D317-392-3362/C907-392-3362. Unctld arpt; prac apch, fleet svc, customs and acft maint NA deicer SAE AMS 1424P Type 1 avbl with 1 hr PN. Civil acft lngd permit req 30 days bfr ldg—D317-552-5282/C907-552-5282.

NOTE: See General Notices—Radiation Areas.

AIRPORT MANAGER: 907-392-3362

COMMUNICATIONS: CTAF 127.2

Ⓡ **ANCHORAGE CENTER APP/DEP CON** 119.1 339.8

RADIO AIDS TO NAVIGATION: NOTAM FILE SYA.

SEMYA (H) (H) VORTACW 109.0 SYA Chan 27 N52°43.10' E174°03.73' 256° 1.9 NM to fld. 67/3E. VORTAC unmonitored 0300-1100Z† Mon-Sat; all day Sun & hol.

TACAN AZIMUTH unusable:

289°-029°

VOR unusable:

289°-029°

DME unusable:

035°-045°

057°-085° byd 35 NM

289°-029°

ILS 110.1 I-SYA Rwy 28. Glideslope unusable for autopilot cpd apchs blw 300'. Unmonitored 0300-1100Z† Mon-Sat; all day Sun and hol.

COMM/NAV/WEATHER REMARKS: For a toll free call to Cold Bay FSS dial 1-800-478-7250. For a toll free call to Kenai FSS dial 1-866-864-1737. Preventive maint schedule, VOR Fri 1800-2000Z†. Wx for all MP is (600/1.5 + 1). TACAN Mon 1800-2000Z†. ILS Tue 1800-2000Z†. CTAF advsy 352.05 unavbl 0300-1100Z† Mon-Sat, Sun and hol. Aft sked arr CTAF advsy 352.05 avbl one hr prior. PMSV METRO remote wx briefings avbl H24—15 OWS

D312-576-9755/C618-256-9755; 2 hr PN. PMSV METRO—Mil tran acft remote briefing avbl from 3 OSS weather Flt Elmendorf Metro DSN 552-4903. Manned obs supplemented by ASOS 1000-0200Z†, Mon-Sat, no Sun or hol. RDO nav fac unmtt 0001-1400Z† dly; cons wkend and hol. Airborne acft declaring acft emerg into Eareckson Air Stn—Eareckson Metro 127.2 or 352.05 durg ops hr; if no answer—Eareckson Radio on CTAF & call

907-392-3505/3606; ensure Anchorage ATC is aware of emerg. As backup Anchorage ATC durg non ops hr shall notify Eareckson Radio on 907-392-3505/3606 of all acft emerg. Dur non ops hr Eareckson Air Stn rqr 30 min PN when psbl. Wx/Afld Ops—D317-392-4005/C907-392-4005.

EAST ELSEK RIVER (See YAKUTAT on page 265)

EDWARD G PITKA SR (See GALENA on page 113)
