

LINCOLN**MILWRICK FLYING M** (3L7) 3 NE UTC-5(-4DT) N44°44.30' W83°22.78'

LAKE HURON

830 NOTAM FILE LAN

RWY 09-27: 2200X90 (TURF)**RWY 09:** Thld dspcd 600'. Pole.**RWY 27:** Trees.

AIRPORT REMARKS: Attended May-Oct irregularly. Arpt CLOSED Nov-Apr and when snow covd. Deer and lrg brds on and invof arpt. No snow removal. Arpt access gate locked, for access call amgr. Rwy 09-27 soft in spring, sfc rough and ireg on rolling trrn. Downslope fm west to east. Rwy 09 and dthr marked with 3' yellow cones. Rwy 09 p-line marked with yellow balls.

AIRPORT MANAGER: 989-335-8076**COMMUNICATIONS:** CTAF/UNICOM 123.0**CLEARANCE DELIVERY PHONE:** For CD ctc Minneapolis ARTCC at 651-463-5588.**LINDEN****PRICES** (9G2) 1 S UTC-5(-4DT) N42°48.46' W83°46.14'

DETROIT

919 B NOTAM FILE LAN

COPTER

RWY 09-27: H3999X75 (ASPH) MIRL 0.3% up W

L-28J

RWY 09: REIL. Thld dspcd 267'. Trees.

IAP

RWY 27: Thld dspcd 800'. Trees.**SERVICE:** S4 **FUEL** 100LL **LGT** Actvt REIL Rwy 09; MIRL Rwy 09-27—CTAF.

AIRPORT REMARKS: Attended irreg. Deer & lrg birds on & invof arpt. Airframe repairs: prior arrangement.

AIRPORT MANAGER: 810-444-3458**COMMUNICATIONS:** CTAF/UNICOM 123.0**FLINT RCO** 122.3 (LANSING RADIO)® **GREAT LAKES APP/DEP CON** 128.55 (1030-0500Z†)® **CLEVELAND CENTER APP/DEP CON** 126.75 (0500-1030Z†) ctc Cleveland ARTCC at 440-774-0229.

CLEARANCE DELIVERY PHONE: For CD ctc Great Lakes Apch at 269-459-3345, when Apch clsd ctc Cleveland ARTCC at 440-774-0229/0490.

RADIO AIDS TO NAVIGATION: NOTAM FILE FNT.

FLINT (VH) (H) VORTACW 116.9 FNT Chan 116 N42°58.01' W83°44.82' 192° 9.6 NM to fld. 771/6W.

TACAN AZIMUTH unusable:

174°-184° wi 15 NM

229°-309° byd 30 NM

310°-228° blo 10,000'

VOR unusable:

070°-090° byd 40 NM

100°-125° byd 40 NM


145°-199° byd 40 NM

Byd 30 NM blo 3,000'

DME unusable:

174°-184° wi 15 NM

Byd 30 NM blo 3,000'

**LIVINGSTON CO/SPENCER J HARDY** (See HOWELL on page 204)