

MARLETTE TOWNSHIP (77G) 1 SW UTC-5(-4DT) N43°18.71' W83°05.46'

DETROIT

895 B NOTAM FILE LAN

L-28J

RWY 10-28: H3795X75 (ASPH) MIRL

IAP

RWY 10: PAPI(P2R)—GA 3.0° TCH 44'. Tree.

RWY 28: PAPI(P2L)—GA 3.0° TCH 45'. Tree.

RWY 01-19: H3500X75 (ASPH) MIRL 0.7% up N

RWY 01: PAPI(P2L)—GA 3.0° TCH 21'.

RWY 19: PAPI(P2L)—GA 3.0° TCH 40'. Tree.

SERVICE: FUEL 100LL LGT ACTIVATE PAPI Rwy 01, 10, 19 and 28;

MIRL Rwy 01-19 & Rwy 10-28—CTAF.

AIRPORT REMARKS: Unattended. Deer & lrg birds on & invof arpt. 100LL

avbl H24 self svc via credit card. Trml bldg acce: 5-3-2-1*.

AIRPORT MANAGER: 810-459-4674

COMMUNICATIONS: CTAF/UNICOM 122.8


② CLEVELAND CENTER APP/DEP CON 127.7

CLEARANCE DELIVERY PHONE: For CD ctc Cleveland ARTCC at
440-774-0224/0490.

RADIO AIDS TO NAVIGATION: NOTAM FILE LAN.

PECK (H) TACAN Chan 87 ECK (114.0) N43°15.35'

W82°43.08' 289° 16.7 NM to fld. 810/7W.

**MARQUETTE/SAWYER RGNL** (SAW)(KSAW) 17 S UTC-5(-4DT) N46°20.95' W87°23.78'

GREEN BAY

1205 B ARFF Index—See Remarks NOTAM FILE SAW MON Airport

H-2K, L-31A

RWY 01-19: H9072X150 (ASPH-GRVD) S-111, D-184, 2S-175,

IAP, AD

2D-312, 2D/2D2-750 PCR 450 F/B/X/T HIRL

RWY 01: MALSR. PAPI(P4L)—GA 3.0° TCH 51'.

RWY 19: REIL. PAPI(P4L)—GA 3.0° TCH 53'. 0.5% down.

RUNWAY DECLARED DISTANCE INFORMATION

RWY 01: TORA-9072 TODA-9072 ASDA-9072 LDA-9072

RWY 19: TORA-9072 TODA-9072 ASDA-9072 LDA-9072

SERVICE: S4 FUEL 100LL, JET A OX 1, 2 LGT When twr clsd

ACTIVATE MALSR Rwy 01; REIL Rwy 19; PAPI Rws 01 and Rwy

19; HIRL Rwy 01-19—CTAF.

AIRPORT REMARKS: Attended 1000-0100Z†. For svc aft hrs call amgr cell
or 810-417-1860. FBO svc aft hrs contact 906-222-3062.

Ficons unmon 0500-0930Z†. Birds and deer on and invof arpt.

PAEW on arpt monitor 119.975 (CTAF). Class I, ARFF Index B. Air

carrier ops are not authorized in excess of 15 minutes before or after

scheduled arrival/dep times without prior coordination with arpt

manager. Unscheduled air carrier operations with more than 30

passenger seats require 48 hour prior permission, call arpt manager

906-346-3308 or 906-364-0939. Index C ARFF avbl with 48 hr

hour prior permission, call arpt manager 906-346-3308 or

906-364-0939. General aviation and charter acft parking avbl at general aviation terminal only, lctd SE corner of arpt.

S half of air carrier terminal ramp not plowed Oct-Apr. Frequent snow removal ops in progress various times Oct-Apr.

Monitor CTAF. North air carrier ramp entrance/exit clsd 15 Nov-15 Apr. Ramp fee may be waived with fuel purchase; for

FBO svc aft hrs call 906-251-0723.

AIRPORT MANAGER: 906-346-3308

WEATHER DATA SOURCES: AWOS-3PT 118.375 (906) 346-5126.


COMMUNICATIONS: CTAF 119.975 UNICOM 122.7

RCO 122.5 (GREEN BAY RADIO)

② MINNEAPOLIS CENTER APP/DEP CON 119.1

TOWER 119.975 (1100-0300Z†) GND CON 121.65

CLEARANCE DELIVERY PHONE: For CD when ATCT is clsd ctc FSS via rco, if una ctc Minneapolis ARTCC at 651-463-5588.



CONTINUED ON NEXT PAGE

CONTINUED FROM PRECEDING PAGE

AIRSPACE: CLASS D svc 1100-0300Z†; other times CLASS E.

RADIO AIDS TO NAVIGATION: NOTAM FILE SAW.

SAWYER (VH) (H) VORW/DME 117.1 SAW Chan 118 N46°21.54' W87°23.85' at fld. 1196/4W.

VOR unusable:

000°-015° byd 40 NM

025°-040° byd 40 NM

075°-085° byd 40 NM

135°-145° byd 40 NM

240°-260° byd 40 NM

275°-300° byd 40 NM

330°-090° byd 10 NM blo 8,000'

DME unusable:

250°-090° byd 30 NM blo 4,500'

ILS 110.1 I-SOU Rwy 01. Class IE. Autopilot cpd apch NA blw 1,360'. Unmonitored.

COMM/NAV/WEATHER REMARKS: No emergency frequencies at twr.

MARSHALL

BROOKS FLD (RMY)(KRMV) 1 S UTC-5(-4DT) N42°15.07' W84°57.33'

941 B TPA-1941(1000) NOTAM FILE RMY

RWY 10-28: H3501X75 (ASPH) S-12.5 MIRL

RWY 10: PAPI(P4L)-GA 4.0° TCH 25'.

RWY 28: PAPI(P4R)-GA 4.0° TCH 37'. Trees.

SERVICE: S4 FUEL 100LL, UL94 LGT Actvt PAPI Rwy 10 & 28;
MIRL Rwy 10-28; nstd perimeter lgts helipad H1-CTAF. Helipad
nstd perimeter lgts due to color.

AIRPORT REMARKS: Attended 1300Z†-dusk, exc major hols. Deer & lrg
birds on & invof arpt. Glider and ultralight activity on and invof arpt
summer months. Ultralight acft fly left hand pattern 500' AGL,
south of Rwy 10-28. For snow removal Helipad H1 call amgr.
Admin bldg aces, press 5-3-2-1.

AIRPORT MANAGER: 269-330-2908

WEATHER DATA SOURCES: AWOS-3 120.025 (269) 781-9070.

COMMUNICATIONS: CTAF/UNICOM 122.8

® GREAT LAKES APP/DEP CON 119.2 (1030-0500Z†)

® CHICAGO CENTER APP/DEP CON 127.55 (0500-1030Z†)

CLEARANCE DELIVERY PHONE: For CD ctc Great Lakes Apch at
269-459-3344, when Apch clsd ctc Chicago ARTCC at
630-906-8921.

RADIO AIDS TO NAVIGATION: NOTAM FILE JXN.

JACKSON (DH) DME 115.45 JXN Chan 101(Y) N42°15.55'

W84°27.51' 269° 22.1 NM to fld. 994.


DME unusable:

180°-210° byd 30 NM blo 3,500'

.....

HELIPAD H1: H100X100 (CONC) S-12.5 RWY LGTS(NSTD)

HELIPORT REMARKS: Nstd perimeter lgts due to color. For snow removal helipad H1 call amgr. 150 ft lgtd water twr 3000 ft
south of helipad.



DETROIT

L-28J

IAP

MASON CO (See LUDINGTON on page 216)