

SEBRING

TRI-CITY (3G6) 1 SE UTC-5(-4DT) N40°54.36' W81°00.00'

1188 NOTAM FILE CLE

Rwy 18-36: H2768X45 (ASPH) LIRL(NSTD)

Rwy 36: Pole.

SERVICE: **FUEL** 100LL **LGT** Actvt NSTD LIRL Rwy 18-36—CTAF. Rwy 18-36 NSTD LIRL due to layout, colors and non-frangible fixtures.

AIRPORT REMARKS: Unattended. Deer, birds, & wildlife on & invof arpt. Fuel avbl upon request, call amgr. Rwy 18-36 excessive cracking, vegetation thru cracks & joints, & uneven rough pavement. Rwy 18 nstd basic due to nrs layout & size. Cntrln faded. Rwy 36 nstd basic due to nrs layout & size. Cntrln faded.

AIRPORT MANAGER: 330-428-1269

COMMUNICATIONS: CTAF 122.9

® CLEVELAND APP/DEP CON 125.5 (1100-0600Z†)

® CLEVELAND CENTER APP/DEP CON 120.6 (0600-1100Z†) ctc Cleveland ARTCC at 440-774-0223.

CLEARANCE DELIVERY PHONE: For CD ctc Cleveland Apch at 216-352-2323, when Apch clsd ctc Cleveland ARTCC at 440-774-0223/0490.

RADIO AIDS TO NAVIGATION: NOTAM FILE CAK.

AKRON (L) (L) VORW/DME 114.4 ACO Chan 91 N41°06.47' W81°12.09' 147° 15.2 NM to fld. 1197/4W.

DME unusable;

Byd 10 NM

DETROIT

L-29B

IAP

SENECA CO (See TIFFIN on page 318)

SHELBY COMMUNITY (12G) 2 WSW UTC-5(-4DT) N40°52.37' W82°41.84'

1120 B NOTAM FILE CLE

Rwy 18-36: H3174X50 (ASPH) S-5 LIRL(NSTD)

Rwy 18: Road.

Rwy 36: Crops.

Rwy 03-21: 1890X125 (TURF)

Rwy 03: Crops.

Rwy 21: Road.

SERVICE: **LGT** SS-SR. Rwy 18-36 NSTD LIRL due to Rwy 18 thr lgts 220 ft fm rwy end; rwy lgts 62 ft fm east edge & 47 ft fm west edge.

AIRPORT REMARKS: Attended 1100-2200Z†. Rwy 18-36 nmrs unsealed cracks and dtrtd pavement, high FOD potential. Rwy 18 and 36 markings faded. Rwy 36 calm wind rwy.

AIRPORT MANAGER: 419-347-1185

COMMUNICATIONS: CTAF/UNICOM 122.8

® CLEVELAND APP/DEP CON 128.35 (1100-0600Z†)

® CLEVELAND CENTER APP/DEP CON 134.9 (0600-1100Z†) ctc Cleveland ARTCC at 440-774-0223.

CLEARANCE DELIVERY PHONE: For CD ctc Cleveland Apch at 216-352-2323, when Apch clsd ctc Cleveland ARTCC at 440-774-0223/0490.

DETROIT

L-29A

IAP

