

MINNEAPOLIS CITY CO (45K) 2 SW UTC-6(-5DT) N39°05.66' W97°43.26'

1246 NOTAM FILE ICT

RWY 16-34: H3970X20 (ASPH)

RWY 16: Trees.

RWY 34: Trees.

AIRPORT REMARKS: Attended Apr–Nov dawn–dusk. Arpt opr daylight hrs only.

Deer on and invof arpt.

AIRPORT MANAGER: 785-392-3300

COMMUNICATIONS: CTA 122.9

⑧ **KANSAS CITY CENTER APP/DEP CON** 134.9

CLEARANCE DELIVERY PHONE: For CD ctc Kansas City ARTCC at

913-254-8508.

RADIO AIDS TO NAVIGATION: NOTAM FILE SLN.

SALINA (WH) (H) VORTACW 117.1 SLN Chan 118 N38°55.51'

W97°37.28' 328° 11.2 NM to fld. 1316/7E.

VOR unusable:

017°-026° byd 40 NM


315°-016° byd 15 NM blo 6,000'

DME unusable:

300°-042° byd 15 NM blo 6,000'

WICHITA

L-101



MOLINE

ELK CO (2K6) 3 NE UTC-6(-5DT) N37°22.86' W96°16.27'

KANSAS CITY

1063 NOTAM FILE ICT

RWY 18-36: H2510X40 (ASPH) 0.4% up N

RWY 36: Pole.

AIRPORT REMARKS: Unattended. Wildlife on and invof arpt. Rwy 18–36 has centerline marking only. Rwy 36 the poles that constitute the controlling obstruction on the right are not visibly marked or lgtd.

AIRPORT MANAGER: 620-374-3597

COMMUNICATIONS: CTA 122.9

CLEARANCE DELIVERY PHONE: For CD ctc Kansas City ARTCC at 913-254-8508.

KANSAS CITY

L-15C

MONTEZUMA MUNI (K17) 2 SW UTC-6(-5DT) N37°35.14' W100°28.21'

WICHITA

L-15C

2780 NOTAM FILE ICT

RWY 17-35: H4000X60 (ASPH) MIRL

RWY 17: Thld dispclc 700'. Road.

RWY 35: Road.

SERVICE: LGT ACTIVATE MIRL Rwy 17–35—CTAF.

AIRPORT REMARKS: Unattended. +6 ft irrigation engine/pump located on Rwy 17–35 W edge near windsock.

AIRPORT MANAGER: 620-846-0550

COMMUNICATIONS: CTA 122.9

CLEARANCE DELIVERY PHONE: For CD ctc Kansas City ARTCC at 913-254-8508.

MORITZ MEML (See BELOIT on page 87)