

FACTORYVILLE**SEAMANS FLD** (9N3) 2 N UTC-5(-4DT) N41°35.36' W75°45.36'

1209 B NOTAM FILE IPT

RWY 04-22: H2500X50 (ASPH) LIRL

SERVICE: FUEL 100LL

AIRPORT REMARKS: Attended 1400-2200Z‡. For svc aft hrs ctc
570-945-5125.

AIRPORT MANAGER: 570-945-5125

COMMUNICATIONS: CTA/UNICOM 122.7

⑧ WILKES-BARRE APP/DEP CON 120.95

CLEARANCE DELIVERY PHONE: For CD ctc Wilkes-Barre Apch at
570-655-2084.

RADIO AIDS TO NAVIGATION: NOTAM FILE AVP.

WILKES-BARRE (L) VORTACW 111.6 LVZ Chan 53 N41°16.37'
W75°41.37' 001° 19.2 NM to fld. 2118/10W.


VOR unusable:

290°-305° byd 15 NM bld 6,000'

NEW YORK

L-30K, 33A

IAP

**FAIRFIELD****MID ATLANTIC SOARING CENTER** (W73) 2 SE UTC-5(-4DT) N39°45.42' W77°21.08'

WASHINGTON

573 NOTAM FILE IPT

RWY 15-33: H2700X50 (ASPH) S-12.5, D-12.5

RWY 15: Trees.

RWY 33: Thld dsplcd 900'. Trees. Rgt tfc.

AIRPORT REMARKS: Attended Sat-Sun dalgt hrs. Unattended Mon-Fri. Arpt ops rstd, in accordance with Temporary Flight
Restriction rules, when P-40 expanded to 10 NM radius. Rwy 15 CLOSED for ldgs. Extensive glider opns. Gliders
occasionally land on turf area adjacent to Rwy 15-33. Rwy 15 not marked with thld or magnetic heading.

AIRPORT MANAGER: 770-540-5503

COMMUNICATIONS: CTAF 123.3

CLEARANCE DELIVERY PHONE: For CD ctc Potomac Apch at 866-709-4993.

COMM/NAV/WEATHER REMARKS: Multicom 123.3 used during glider activity.

FARMERS PRIDE (See FREDERICKSBURG on page 278)