

WEST KINGSTON

RICHMOND (Ø8R) 3 W GMT-5(-4DT) N41°29.37' W71°37.24'

NEW YORK

130 NOTAM FILE BDR

RWY 11-29: H2129X30 (ASPH) LIRL(NSTD)

RWY 11: Trees.

RWY 29: TRCV(TRIL)—GA 5.5° TCH 21'. Thld dspcd 130'. Tree.

SERVICE: S4 **FUEL** 100LL **LGT** ACTIVATE LIRL Rwy 11-29 and windsock lgts—CTAF. Rwy 11-29 NSTD LIRL located 30' from edge of pavement. Rwy 29 dspcd thld lgtd and marked with white bar and number. Rotating bcn OTS indef.

AIRPORT REMARKS: Attended 1400-2200Z†. Irregular hrs of opr. Call 401-783-1498 for acft requiring fuel. Ultralights on and invof arpt. Deer and birds on and invof arpt. Rwy 11 CLOSED ngts. +40' drop-off 150' from Rwy 29 end. +10' drop-off 200' from Rwy 11 end. Rwy has non-std safety area, ctc AMGR for dtls.

AIRPORT MANAGER: 401-783-1498

COMMUNICATIONS: CTAF/UNICOM 122.8

CLEARANCE DELIVERY PHONE: For CD ctc Providence Apch at 401-738-8945, when Apch clsd ctc Boston ARTCC at 603-879-6859.

WESTERLY STATE (WST)(KWST) 2 SE UTC-5(-4DT) N41°20.98' W71°48.21'

NEW YORK

81 B NOTAM FILE WST

L-33C, 341

RWY 07-25: H4010X100 (ASPH-GRVD) S-30, D-60 MIRL

IAP

0.7% up NE

RWY 07: MALSf. PAPI(P4R)—GA 3.5° TCH 46'. Trees.

RWY 25: REIL. VASI(V2L)—GA 3.5° TCH 36'. Trees.

RWY 14-32: H3960X75 (ASPH) S-12.5 MIRL 0.6% up SE

RWY 14: REIL. PAPI(P4L)—GA 4.0° TCH 40'. Trees.

RWY 32: REIL. PAPI(P4L)—GA 4.0° TCH 40'. Thld dspcd 750'. Trees.

SERVICE: S4 **FUEL** 100LL, JET A **LGT** Dusk-Dawn. ACTVT MALSf Rwy 07; REIL Rwy 25, Rwy 14 and Rwy 32; PAPI Rwy 07, Rwy 14 and Rwy 32; VASI Rwy 25; MIRL Rwy 07-25 and Rwy 14-32—CTAF. Rwy 07 PAPI U/S. Rwy 14 PAPI U/S.

NOISE: Noise abatement procs in efct ctc amgr at 401-691-2265. Arpt lctd in noise sensitive area. Populated areas to the S & W should be avoided.

AIRPORT REMARKS: Attended 1300-2200Z† Sun-Sat Jun-Sep, 1300-2100Z† Sun-Sat Oct-May. Parachute Jumping. Deer and birds on and invof arpt. Self svc 100LL avbl 24 hrs. Gldrs opr fm arpt on intrmt basis. Hel tours & banner tow ops on airfield blw 1000 ft alg southern coast of Rhode Island. For after hrs terminal apron access ctc arpt manager 401-691-2265. Rwy 07-25 is the preferred calm wind rwy. Rwy conds may not be mnt or rptd when AP is unatndd. Ctc RI AP Corporation Ops 401-691-2265. Rwy 07-25 uneven pavement approximately 1,000' from AER 25 thld. Ctc arpt manager 401-691-2265. Rwy 07 tempo dthr 375 ft. Rwy 14 tempo dthr 595 ft. Overnight parking fee. Ldg fee for commercial and non Rhode Island registered acft.

AIRPORT MANAGER: 401-691-2265

WEATHER DATA SOURCES: ASOS 132.375 (401) 596-9543.

COMMUNICATIONS: CTAF/UNICOM 123.0

® **PROVIDENCE APP/DEP CON** 119.45 (South of ORW) (Sun-Fri 1030-0530Z†, Sat 1030-0500Z†) other times ctc

BOSTON CENTER APP/DEP CON 124.85

CLEARANCE DELIVERY PHONE: For CD ctc Providence Apch at 401-738-8945, when Apch clsd ctc Boston ARTCC at 603-879-6859.

RADIO AIDS TO NAVIGATION: NOTAM FILE GON.

GROTON (T) (T) VORW/DME 110.85 GON Chan 45(Y) N41°19.82' W72°03.12' 098° 11.3 NM to fld. 9/14W.

VOR portion unusable:

241°-265° blo 5,000'

DME unusable:

355°-019° blo 3,000'

LOC/DME 108.9 I-RLS Chan 26 Rwy 07. LOC unmonitored.

