

CLEARWATER

TOKETEETEE STATE (3S6) 2 S UTC-8(-7DT) N43°13.41' W122°25.27'

KLAMATH FALLS

3361 NOTAM FILE MMV

RWY 11-29: 5350X60 (TURF) 2.4% up SE

RWY 11: Trees.

RWY 29: Trees.

AIRPORT REMARKS: Unattended. Arpt CLOSED from 1 Nov-1 May. Elk, deer and turkey on and in/ov arpt. Arpt on West side of Cascades and affected by wx West. Best info on arpt thru US Forest svc Roseburg, or Icl FBO at Roseburg. Rwy 11-29 graded, 60' wide, shoulders rough and rutted. Rwy 11-29 has +120' trees 250' either side of centerline. Rwy 11-29 thlds outlined with white tires. Trees 4'-30' along south side of rwy within 50' of centerline. Sfc conds not rptd.

AIRPORT MANAGER: 503-378-4880

COMMUNICATIONS: CTAF 122.9

CLEARANCE DELIVERY PHONE: For CD ctc Seattle ARTCC at 253-351-3694.

COLUMBIA GORGE RGNL/THE DALLES MUNI (See THE DALLES on page 215)

COLUMBIA N45°35.32' W122°36.68' NOTAM FILE PDX.

SEATTLE

(H) **TACAN** 109.2 CBU Chan 29 at Portland Intl. 22/15E.

H-1B, L-1C

TACAN unusable:

025°-035° byd 30 NM blo 9,500'

035°-055° byd 20 NM blo 9,500'

105°-145° byd 65 NM blo 18,000'

125°-135° byd 15 NM blo 8,500'

160°-255° byd 15 NM blo 10,500'

255°-275° byd 20 NM blo 8,500'

DME unusable:

025°-035° byd 30 NM blo 9,500'

035°-055° byd 20 NM blo 9,500'

105°-145° byd 65 NM blo 18,000'

125°-135° byd 15 NM blo 8,500'

160°-255° byd 15 NM blo 10,500'

255°-275° byd 20 NM blo 8,500'

CONDON STATE PAULING FLD (3S9) 1 NE UTC-8(-7DT) N45°14.79' W120°09.99'

SEATTLE

2911 B NOTAM FILE MMV

L-13A

RWY 07-25: H3500X60 (CONC) S-12 MIRL

RWY 07: REIL. PAPI(P4L)—GA 3.0° TCH 40'. Road.

RWY 25: REIL. PAPI(P4L)—GA 3.0° TCH 40'.

SERVICE: LGT ACTIVATE REIL Rwy 07 and Rwy 25; MIRL Rwy 07-25, PAPI Rwy 07 and Rwy 25—CTAF.

AIRPORT REMARKS: Unattended. Surface conditions not reported. Heavy AG ops Feb-Jun.

AIRPORT MANAGER: 503-378-4880

COMMUNICATIONS: CTAF 122.9

CLEARANCE DELIVERY PHONE: For CD ctc Seattle ARTCC at 253-351-3694.

RADIO AIDS TO NAVIGATION: NOTAM FILE DLS.

KLICKITAT (VH) (DH) VORW/DME 112.3 LTJ Chan 70 N45°42.82' W121°06.05' 104° 48.4 NM to fld. 3220/21E.


VOR unusable:

003°-017° byd 40 NM

192°-198° byd 40 NM

207°-211° byd 40 NM

306°-311° byd 40 NM



CORNELIUS

SKYPORT (4S4) 3 N UTC-8(-7DT) N45°34.96' W123°03.17'

SEATTLE

174 NOTAM FILE MMV

RWY 16-34: 2000X45 (TURF)

RWY 16: Trees. Rgt tfc.

RWY 34: Thld dsplcd 200'. Road.

AIRPORT REMARKS: Attended 1400-0400Z. Helicopter and ultralight ops prohibited. Rwy 16-34 rwy ends marked with half barrels. Rwy 34 dsplcd thld marked with L-shaped boards.

AIRPORT MANAGER: 503-648-9311

COMMUNICATIONS: CTAF 122.9

CLEARANCE DELIVERY PHONE: For CD ctc Portland Apch at 503-493-7545.