

DRIGGS/REED MEML (DIJ)(KDIJ) 1 N UTC-7(-6DT) N43°44.78' W111°05.48'

6257 B TPA—See Remarks NOTAM FILE DIJ

RWY 04-22: H7301X100 (ASPH) S-30, D-75 PCN 28 F/B/X/T

MIRL 1.3% up NE

RWY 04: PAPI(P4L)—GA 3.5° TCH 40'.**RWY 22:** REIL. PAPI(P4L)—GA 3.5° TCH 40'. Rgt tfc.

SERVICE: S6 **FUEL** 100LL, JET A+ **OX** 1, 2 **LGT** ACTVT REIL Rwy 22 and MIRL Rwy 04-22—CTAF. PAPI Rwys 04 and 22 oprs consly. Rwy 22 PAPI unusbl byd 4 nm due to trmn.

AIRPORT REMARKS: Attended Oct-May 1500-0000Z, Jun-Sep 1400-0200Z. Sailplane ops heavy dur summer months.

Snowplowing is oprnl durg bus hrs. Hel no hover taxi. TPA: Powered acft use rgt tfc to Rwy 22. Calm wind ldg on Rwy 22. Gliders utilize rgt tfc for Rwy 04 and left tfc for Rwy 22. 3000' X 150' turf ldg area marked with white cones btn Rwy 04-22 and twy ltd to tailwheel acft with wingspan 49' or less. Aux pwr units are not to be started until thirty mins prior to planned tkof time. Aux pwr units oprg byd thirty mins will be chrgd \$100 per ten mins. Ldg fee. Acft ovr 9000 lbs: \$6.00 per 1000 lbs of max certd ldg wt rounded to the nrst 1000 lbs. Acft ovr 9000 lbs: \$8.00 per 1000 lbs of mlw fm the hrs of 10pm to 7am local. For more info ctc amgr.

AIRPORT MANAGER: 607-341-8041**WEATHER DATA SOURCES:** AWOS-3PT 120.775 (208) 354-6661.**COMMUNICATIONS:** CTAF/UNICOM 122.7® **SALT LAKE CENTER APP/DEP CON** 128.35**CLEARANCE DELIVERY PHONE:** For CD ctc Salt Lake ARTCC at 801-320-2568.**RADIO AIDS TO NAVIGATION:** NOTAM FILE BOI.**DUBOIS (VH) (H) VORTACW** 116.9 DBS Chan 116 N44°05.33' W112°12.56' 098° 52.7 NM to fld. 4920/15E.

VOR unusable:

003°-013° byd 40 NM blo 15,000'

003°-013° byd 65 NM blo 18,000'

014°-070° byd 40 NM

105°-110° byd 40 NM

122°-129° byd 40 NM

133°-150° blo 7,600'

225°-264° byd 40 NM

265°-275° byd 40 NM blo 16,000'

265°-275° byd 73 NM blo 18,000'

276°-284° byd 40 NM

285°-295° byd 40 NM blo 13,600'


285°-295° byd 54 NM

296°-327° byd 40 NM

328°-338° byd 40 NM blo 12,000'

328°-338° byd 51 NM

339°-002° byd 40 NM


DUBOIS MUNI (U41) 1 SE UTC-7(-6DT) N44°09.74' W112°13.24'

5123 NOTAM FILE BOI

RWY 16-34: 4600X100 (GRVL-DIRT)**RWY 16:** Road.**RWY 34:** Rgt tfc.

AIRPORT REMARKS: Unattended. No winter maintenance. Rwy 16-34—60 ft grvl strip is cntrd btn the 300 ft arpt bdry mkr.

Rwy 16-34 cone bdry mkr 125 ft each side of rwy cntrln and wood panels acrs both trhs.

AIRPORT MANAGER: 208-351-5459**COMMUNICATIONS:** CTAF 122.9**CLEARANCE DELIVERY PHONE:** For CD ctc Salt Lake ARTCC at 801-320-2568.

SALT LAKE CITY