

TISHOMINGO AIRPARK (0F9) 2 S UTC-6(-5DT) N34°11.91' W96°40.47'

647 B NOTAM FILE MLC

RWY 17-35: H3100X60 (ASPH) S-12 RWY LGTS(NSTD)

RWY 17: Trees.

RWY 35: Trees.

SERVICE: LGT Nstd solar LIRL Rwy 17-35 SS-SR. Rwy 17-35 nstd due to thld lghts all red and edge lghts all yellow. Rotating bcn OTS indef.

AIRPORT REMARKS: Unattended.

AIRPORT MANAGER: (580) 371-8605

COMMUNICATIONS: CTAF 122.9

CLEARANCE DELIVERY PHONE: For CD ctc Fort Worth ARTCC at 817-858-7584.

RADIO AIDS TO NAVIGATION: NOTAM FILE ADM.

ARDMORE (VH) (H) VORTACW 116.7 ADM Chan 114 N34°12.70' W97°10.09' 086° 24.6 NM to fld. 937/6E.


VOR unusable:

150°-160°

302°-346°

DALLAS-FT WORTH

L-17C



TULSA

HARVEY YOUNG (1H6) 8 E UTC-6(-5DT) N36°08.34' W95°49.50'

KANSAS CITY

750 B NOTAM FILE MLC

RWY 17-35: H2580X40 (ASPH)

RWY 17: Trees.

RWY 35: Trees.

RWY N-S: 2580X80 (TURF)

RWY N: Trees.

RWY S: Trees.

SERVICE: S2

AIRPORT REMARKS: Unattended. Birds and ultralights on and invof arpt. Rwy 17 hel ops R tfc. Twys thin and soft in hot weather.

Rwy 17-35 cracking and raveling. Rwy 17 marking faded. Rwy 35 markings faded and unreadable. Rwy N-S rough and uneven.

AIRPORT MANAGER: 918-951-3481

COMMUNICATIONS: CTAF/UNICOM 122.8

CLEARANCE DELIVERY PHONE: For CD ctc Tulsa Apch at 918-831-6714/6720.