

**DECATUR MUNI** (LUD)(KLUD) 2 N UTC-6(-5DT) N33°15.26' W97°34.83'

1047 B NOTAM FILE LUD

**RWY 17-35:** H4200X60 (ASPH) S-12.5, D-17 MIRL

RWY 17: REIL, PAPI(P2L)—GA 3.5° TCH 23°. Tree.

RWY 35: PAPI(P2L)—GA 3.5° TCH 40°. P-line. Rgt tfc.

**SERVICE:** S4 FUEL 100LL, JET A LGT Dusk-Dawn. MIRL Rwy 17-35 preset low intst; to incr intst actvt—CTAF.

**AIRPORT REMARKS:** Attended 1400-2300Z. Deer and wildlife on and invof arpt. Gnd drops sharply 160' north of Rwy 17 thr. Rwy 17-35 extensive pavement cracking. Due to rwy elev chg, acft not vsb at opposite end.

**AIRPORT MANAGER:** 940-627-2855

**WEATHER DATA SOURCES:** AWOS-3 118.225 (940) 627-2365.

**COMMUNICATIONS:** CTAf/UNICOM 122.8

⑧ LONE STAR APP/DEP CON 118.1

**CLEARANCE DELIVERY PHONE:** For CD ctc Regional Apch at 972-615-2799.

**RADIO AIDS TO NAVIGATION:** NOTAM FILE FTW.


**BOWIE (H) (H) VORTACW** 117.15 UKW Chan 118(Y) N33°32.15' W97°49.28' 138° 20.8 NM to fld. 1102/6E.

**DALLAS-FT WORTH**

COPTER

L-17C, A

IAP



**HERITAGE CREEK AIRSTRIp** (58T) 9 SE UTC-6(-5DT) N33°09.96' W97°28.79'

**DALLAS-FT WORTH**

883 NOTAM FILE FTW

**RWY 13-31:** 3000X60 (TURF) LIRL 0.8% up NW

RWY 13: Tree.

RWY 31: Tree. Rgt tfc.

**SERVICE:** S4 LGT ACTVT LIRL Rwy 13-31 —CTAF. Rwy defined by white "L" markers on each corner—nights: two lights each side of cntrln mark rwy ends.

**AIRPORT REMARKS:** Unattended. Deer and birds on and invof arpt. RCO ctl model acft ops on arpt. All acft monitor CTAF due to the close proximity of Rhome Meadows arpt T76. Rwy 31 right tfc for fixed wing acft; remain east of the rwy.

**AIRPORT MANAGER:** 817-988-9745

**COMMUNICATIONS:** CTAf 122.9

**CLEARANCE DELIVERY PHONE:** For CD ctc Regional Apch at 972-615-2799.

**DALLAS-FT WORTH**

COPTER

**LAZY G BAR RANCH** (09T) 5 NE UTC-6(-5DT) N33°16.88' W97°29.80'

**DALLAS-FT WORTH**

931 NOTAM FILE FTW

**RWY 17-35:** 1600X40 (TURF-DIRT)

RWY 17: Tree. Rgt tfc.

RWY 35: Tree.

**AIRPORT REMARKS:** Unattended. Livestock on and invof arpt. For fld condition call to confirm rwy is clear of livestock. Rwy 17-35 rough, rolling gradient. No line of sight btween rwy ends. Rwy 17-35 center 20 ft mowed.

**AIRPORT MANAGER:** 719-221-7993

**COMMUNICATIONS:** CTAf 122.9

**CLEARANCE DELIVERY PHONE:** For CD ctc Regional Apch at 972-615-2799.

**TRIPLE-ACE FLD** (35X) 2 NE UTC-6(-5DT) N33°15.11' W97°33.21'

**DALLAS-FT WORTH**

1010 NOTAM FILE FTW

**RWY 02-20:** 1271X40 (TURF)

RWY 02: Road. Rgt tfc.

RWY 20: Fence.

**AIRPORT REMARKS:** Unattended. No student trng. Rwy soft aft rain, call for ficons.

**AIRPORT MANAGER:** 940-627-6800

**COMMUNICATIONS:** CTAf 122.8

**COMM/NAV/WEATHER REMARKS:** Acft orgn into or out of arpt will use Decatur Arpt freq 122.8 to communicate with Decatur Arpt tfc.