

DALLAS—FT WORTH

590 B TPA—See Remarks NOTAM FILE GPM

RWY 18-36: H4001X75 (CONC) S-30 MIRL

RWY 18: VASI(V4L)—GA 3.0° TCH 26'. Bldg.

RWY 36: REIL. VASI(V4L)—GA 4.0° TCH 37'. Road. Rgt tfc.

SERVICE: S4 **FUEL** 100LL, JET A **LGT** MIRL Rwy 18-36 preset low
intst; to incr intst and ACTVT REIL Rwy 36 aft ATCT clsd—CTAF.

AIRPORT REMARKS: Attended Mar-Oct Mon-Sat 1400-0200Z+, Nov-Feb Mon-Sat 1400-0200Z+, Sun 1400-0100Z+. Extsvs helc tpc west side of aprt. 165' water trw, 1/4 mile west of Rwy 18-36, TPA=1400 (812) fixed wing, 1200 (612) rotary wing. West grass for rotary wing use only. No ADS-B billing or ldg fees. GA tsnt ramp free for short term only.

AIRPORT MANAGER: 972-237-7591

WEATHER DATA SOURCES: AWOS-3P 118.475 (972) 606-1433.

COMMUNICATIONS: CTAF 128.55 UNICOM 123.075

® LONE STAR APP/DEP CON 135,975

TOWER 128.55 (1200-0200Z dalgt time; 1400-0000Z standard time) **GND CON** 121.15

CLEARANCE DELIVERY PHONE: For CD when ATCT is clsd ctc Regional Apch
at 972-615-2799.

AIRSPACE: CLASS D svc 1200-0200Z dalgt time, 1400-0000Z standard time; other times CLASS G.

RADIO AIDS TO NAVIGATION: NOTAM FILE FTW.

MAVERICK (VH) (H) VORW/DME 113.1 TTT Chan 78 N32°52.15' W97°02.43' 176° 10.2 NM to fld. 536/6E.

All acft arriving DFW are requested to turn DME off until departure due to traffic overload of Maverick DME

DME unusable:


180°–190° byd 10 NM

240°–260° byd 20 NM blo 3,500'

VOR unusable:

105°–110° byd 40 NM

HELIPAD H1: H50X50 (CONC) PERIMETER LGTS



GRANITE SHOALS/ BOB SYLVESTER AIRPARK (2G5) 1 E UTC-6(-5DT) N30°35.36' W98°22.22' SAN ANTONIO

860 NOTAM FILE 2G5

RWY 02-20: 2000X50 (TURF-DIRT)

RWY 02: Trees.

RWY 20: Road.

AIRPORT REMARKS: Unattended. Arpt is dalg use only. Nmrs deer often on rwy.

AIRPORT MANAGER: 830-598-2424

COMMUNICATIONS: CTAF 122.9

CLEARANCE DELIVERY PHONE: For CD ctc Houston ARTCC at 281-230-5622.

GREATER MORRIS CO (See DAINGERFIELD on page 300)**GREEN ACRES AIRFIELD** (See PAMPA on page 410)