

MOUNT OLIVE MUNI (W40) 3 NE UTC-5(-4DT) N35°13.29' W78°02.32'

167 B NOTAM FILE RDU

CHARLOTTE

H-9C, L-35B, 36F

IAP

RWY 05-23: H5254X75 (ASPH) S-20 MIRL

RWY 05: PAPI(P2L)—GA 3.5° TCH 43'. Trees.

RWY 23: PAPI(P2L)—GA 3.5° TCH 43'. Thld displcd 254'. Road.

SERVICE: S4 **FUEL** 100LL, JET A1+ **OX** 3, 4 **LGT** After SS ACTVT and incr instst MIRL Rwy 05-23—CTAF. ACTVTPAPI Rwy 05 and Rwy 23—CTAF.

AIRPORT REMARKS: Attended 1300-2300Z†. Unattended on major hol. For svc after hrs call 252-234-7778 or 252-289-7778. For AVGAS and Jet A - 24 hr self svc with credit card. -5' drainage ditch 100' left of cntrln of Rwy 05. Rwy 05 +200' AM radio twr aprx 6000' SW of rwy end on cntrln. Low level mil activity near arpt. For collision avoidance ctc Seymour AFB 119.7.

AIRPORT MANAGER: 919-635-1471

WEATHER DATA SOURCES: AWOS-3P 120.075 (919) 658-8067.

COMMUNICATIONS: CTAF/UNICOM 122.8

® **SEYMOUR JOHNSON APP/DEP CON** 119.7 (1200-0400Z†) other times ctc

® **WASHINGTON CENTER APP/DEP CON** 123.85

CLEARANCE DELIVERY PHONE: For CD ctc Washington ARTCC at 703-771-3587.

RADIO AIDS TO NAVIGATION: NOTAM FILE ISO.

KINSTON (VL) (L) VORTAC 117.5 ISO Chan 122 N35°22.26' W77°33.50' 254° 25.2 NM to fld. 70/5W.

VOR unusable:

020°-025° byd 40 NM

040°-115° byd 40 NM

145°-155° byd 40 NM

175°-185° byd 40 NM

183°-215° byd 30 NM blo 5,000'

200°-206° byd 40 NM

207°-214° byd 59 NM

215°-238° blo 3,500'

215°-238° byd 6 NM

238°-258° byd 30 NM blo 5,000'

239°-265° byd 40 NM

280°-290° byd 40 NM

295°-308° byd 40 NM

309°-319° byd 31 NM

320°-325° byd 40 NM

335°-340° byd 40 NM

345°-347° byd 40 NM

348°-358° byd 20 NM

TACAN AZIMUTH unusable:

183°-215° byd 30 NM blo 5,000'

DME unusable:

183°-215° byd 30 NM blo 5,000'

