

OCRACOKE ISLAND (W95) 1 E UTC-5(-4DT) N35°06.07' W75°57.96'
4 B NOTAM FILE RDU
RWY 06-24: H2998X60 (ASPH) S-30

CHARLOTTE
L-35C
IAP

RWY 06: Brush.

RWY 24: Brush.

AIRPORT REMARKS: Unattended. Arpt CLOSED 30 min after SS until 30 min before SR. Rwy not lgtd-night ops prohibited.
Flocks of seagulls on and near rwy around standing water after heavy rains. Rwy subj residual flooding durg and aft heavy rain. High speed low level mil ops invof arpt. Rwy safety area is loose sand; not suitable for acct. Arpt is within Cape Hatteras National Seashore. Maintain 2000' vertical and horizontal distance from seashore beaches. Key code access to pilot lounge.

AIRPORT MANAGER: 252-475-9000

COMMUNICATIONS: CTAF 122.9

®CHERRY POINT APP/DEP CON 119.75

CLEARANCE DELIVERY PHONE: For CD cto Washington ARTCC at 703-771-3587.

RADIO AIDS TO NAVIGATION: NOTAM FILE EWN.

NEW BERN (VL) (L) VOR/DME 113.6 EWN Chan 83 N35°04.39' W77°02.70' 096° 53.2 NM to fld. 16/8W.

VOR unusable:

- 000°-008° byd 40 NM
- 009°-019° byd 40 NM blo 4,000'
- 009°-019° byd 48 NM
- 020°-044° byd 40 NM
- 045°-055° byd 40 NM blo 4,000'
- 045°-055° byd 49 NM
- 056°-104° byd 40 NM
- 105°-160° blo 5,000'
- 161°-167° byd 40 NM
- 168°-187° byd 30 NM
- 188°-226° byd 40 NM
- 221°-260° byd 30 NM blo 6,000'
- 227°-237° byd 40 NM blo 6,000'
- 227°-237° byd 65 NM
- 238°-271° byd 40 NM
- 261°-271° byd 30NM blo 3,000'
- 272°-290° byd 30 NM
- 291°-292° byd 40 NM
- 293°-306° byd 30 NM
- 307°-332° byd 40 NM
- 333°-351° byd 30 NM
- 352°-359° byd 40 NM

DME unusable:

- 109°-118° byd 30 NM
- 291°-320° byd 30 NM
- 355°-005° byd 30 NM

HELIPAD H1: H100X100 (CONC) PERIMETER LGTS

HELIPAD H1: Trees.

HELIPORT REMARKS: Helipad for emerg ops only. H1 best apch from NE or SW. Actvt Helipad perimeter lgts only—CTAF. Actvt heli beacon—CTAF. Windsock for helipad lgtd. 30' power line along NC Hwy 12 NW of helipad.

ODELL WILLIAMSON MUNI (See OCEAN ISLE BEACH on page 343)