

COLUMBIA

COLUMBIA METRO (CAE)(KCAE) 5 SW UTC-5(-4DT) N33°56.33' W81°07.17'

CHARLOTTE

236 B LRA Class I, ARFF Index B NOTAM FILE CAE MON Airport

H-9B, 12G, L-24I

RWY 11-29: H8601X150 (CONC-GRVD) S-120, D-239, 2S-175,

IAP, AD

2D-478, 2D/2D2-700 PCR 740 R/A/W/T HIRL CL

RWY 11: ALSF2. TDZL. PAPI(P4L)—GA 3.0° TCH 71'. RVR-TMR**RWY 29:** MALSR. PAPI(P4L)—GA 3.0° TCH 78'. RVR-TMR 0.5% up.**RWY 05-23:** H8001X150 (ASPH-CONC-GRVD) S-120, D-242,

2S-175, 2D-487, 2D/2D2-675 PCR 750 R/A/W/T HIRL

RWY 05: MALSR. PAPI(P4R)—GA 3.0° TCH 73'. RVR-T 0.4% down.**RWY 23:** REIL. PAPI(P4L)—GA 3.0° TCH 69'. RVR-T Thld displcd

1000'. Tree.

RUNWAY DECLARED DISTANCE INFORMATION**RWY 05:** TORA-8001 TODA-8001 ASDA-7001 LDA-7001**RWY 11:** TORA-8601 TODA-8601 ASDA-8601 LDA-8601**RWY 23:** TORA-8001 TODA-8001 ASDA-8001 LDA-7001**RWY 29:** TORA-8601 TODA-8601 ASDA-8506 LDA-8506**SERVICE:** S4 **FUEL** 100LL, JET A **OX** 1, 3 **LGT** Rwy 11 ALSF2 also operates as SSALR.**NOISE:** Noise abatement proc: No turns blw 1000 ft for turbine eng acft unless dctd by ATC.**AIRPORT REMARKS:** Attended continuously. Acft ldg with explosives obtain PPR from arpt ops 803-822-5050. Due to proximity and rwy alnmt aircrews have mistaken CUB (Rwy 13-31) for CAE (Rwy 11-29) which is 6 miles NE. Rwy 05-23 cntr 75 ft is conc, entire len of rwy. Helipad H1 located north of Taxilane E, east of Twy E3. Oprn of ultralight vehicles prohibited. Sports complex with numerous flood lgts aprxly 6500 ft from apch end Rwy 11. Rwy 05 200 ft x 200 ft blast pad. Rwy 11 220 ft x 400 ft blast pad; Rwy 29 220 ft x 400 ft blast pad. Fee for coml acft over 15,000 lbs.**AIRPORT MANAGER:** (803) 822-5015**WEATHER DATA SOURCES:** ASOS (803) 369-6879 LLWAS.**COMMUNICATIONS:** ATIS 120.15 UNICOM 122.95**COLUMBIA RCO** 122.1R 114.7T (ANDERSON RADIO)® **COLUMBIA APP/DEP CON** 124.15 (110°-289°) 133.4 (290°-109°)**TOWER** 119.5 **GND CON** 121.9 **CLNC DEL** 119.75**AIRSPACE:** CLASS C svc ctc **APP CON**.**RADIO AIDS TO NAVIGATION:** NOTAM FILE CAE.**(VH) (H) VORTAC** 114.7 CAE Chan 94 N33°51.44' W81°03.23' 328° 5.9 NM to fld. 404/2W.

VOR unusable:

000°-073° byd 35 NM blo 6,000'

200°-234° byd 12 NM blo 3,000'

235°-245° byd 12 NM blo 6,000'

246°-289° byd 12 NM blo 3,000'

290°-305° byd 12 NM blo 2,400'

306°-344° byd 30 NM

345°-359° byd 10 NM blo 5,000'

ILS 108.95 I-GJC Rwy 05. Class IE.**ILS/DME** 110.3 I-CAE Chan 40 Rwy 11. Class IIIE.**ILS** 108.3 I-VYK Rwy 29. Class IE.• • • • •
HELIPAD H1: H50X50 (CONC) PERIMETER LGTS