

ATLANTA
H-6K, 9A, 12F, L-18I
IAP AD

RWY 21: PAPI(P41)—GA 3.0° TCH 55'. Tree.

HOOK BAK-12B(B) (1510 FT). RWY 28

AIRPORT REMARKS: Attended continuously. I

MILITARY REMARKS: CAUTION Bird Hazard, Ctc Base Ops on 360.975 for current bird watch cond. BASH Phase II bird act is durg Apr and fm 1 Sep to 31 Dec. **ANG** Ongoing constr on ramp. Ctc Base Ops for tax/prkg instrns DSN 358-9255 or C334-394-7255. Rwy cond code not reported. Transport act ltd to min thrust while on ANRG ramp. Cones blocking throat of ANRG ramp. Ctc Base Ops prior to entering ANRG ramp for removal. lnbld for ANRG ctc BAMA OPS 15 min prior to ldg. Acft prk extremely ltd ctc Base OPS for parking instr. Tsnt parking extremely limited. PPR for use of ANRG ramp ctc ANRG OPS DSN 358-9255/9256 C334-394-7255/7256. **ARGN** Fw wing act inbound to ARNG ramp ctc ARNG 10 min prior to ETA and upon entry Twy D. L-3 (C-12) maint avbl on call, C334-280-4890 communications.

ILS 108.5 I-DLV Rwy 28. Class IA. OM unmonitored. Unmonitored when ATCT clsd. LOC unusable byd 17° right of course

HELIPAD H1: H90X90 (CONC)

MOONTOWN (See HUNTSVILLE on page 62)

MOTON FLD MUNI (See TUSKEGEE on page 80)