
MARKLEEVILLE**ALPINE CO** (M45) 3 N UTC-8(-7DT) N38°44.09' W119°46.02'**SAN FRANCISCO**

5872 TPA-6672(800) NOTAM FILE RNO

L-9A**RWY 17-35:** H4443X50 (ASPH) 1.0% up S**RWY 17:** Hill.**RWY 35:** Rgt t/c.**AIRPORT REMARKS:** Unattended. No snow removal, arpt CLOSED when snow on rwy. Soil conditions off rwy is poor in wet conditions. Call public works for additional information 530-694-2140 extension 0. Large stones along edge of rwy off graded surface. Rwy 17-35 ltd by arpt opr to 4,800 lbs single wheel, 9,600 lbs dual wheel. Rwy 17-35 loose grvl on rwy.**AIRPORT MANAGER:** 530-694-2140**COMMUNICATIONS:** CTAF 122.9**CLEARANCE DELIVERY PHONE:** For CD ctc Oakland ARTCC at 510-745-3380.**RADIO AIDS TO NAVIGATION:** NOTAM FILE RNO.**MUSTANG (VH) (H) VORTACW** 117.9 FMG Chan 126 N39°31.88' W119°39.36' 170° 48.0 NM to fld. 5950/16E.

VOR unusable:

002°-012° byd 40 NM blo 19,000'

013°-022° byd 40 NM blo 10,300'

013°-022° byd 53 NM

023°-045° byd 40 NM

079°-113° byd 40 NM

114°-124° byd 40 NM blo 10,000'

114°-124° byd 52 NM

125°-145° byd 40 NM

153°-172° byd 40 NM blo 15,000'

153°-172° byd 52 NM blo 18,000'

173°-186° byd 40 NM

187°-197° byd 40 NM blo 15,000'

187°-197° byd 66 NM

198°-212° byd 40 NM

200°-230° byd 30 NM blo 13,000'

213°-223° byd 40 NM blo 18,000'

224°-304° byd 40 NM

327°-339° byd 40 NM blo 14,000'

356°-001° byd 40 NM

TACAN AZIMUTH unusable:

200°-230° byd 30 NM blo 13,000'

DME unusable:

200°-230° byd 30 NM blo 13,000'