

OROVILLE MUNI (OVE)(KOVE) 3 SW UTC-8(-7DT) N39°29.27' W121°37.32'

SAN FRANCISCO

194 B TPA—994(800) NOTAM FILE OVE

H-3B, L-2G

RWY 02-20: H6020X100 (ASPH) S-47, D-90 HIRL

IAP

RWY 02: REIL. PAPI(P2L)—GA 3.0° TCH 44'.

RWY 20: REIL. PAPI(P2L)—GA 3.0° TCH 40'.

RWY 13-31: H3540X100 (ASPH) S-19, D-31 HIRL 0.5% up NW

RWY 13: PAPI(P2L)—GA 3.0° TCH 39'.

RWY 31: PAPI(P2L)—GA 3.0° TCH 29'. Trees.

SERVICE: S3 **FUEL** 100LL, JET A **LGT** ACTVT REIL Rwy 02 and 20;

PAPI Rwy 02, 13, 20 and 31; HIRL Rwy 02-20 and Rwy

13-31—CTAF. VGSi Rwy 20 does not provide obstruction clearance
byd 3 NM.

AIRPORT REMARKS: Attended Mon-Sat 1600-0100Z†. For Arpt
information Mon-Fri ctc (530) 538-2490. Firefighting acft invof arpt
May-Oct. Twy from Rwy 02-20 to golf course/restaurant tiedowns
20' wide with no shoulders.

AIRPORT MANAGER: 530-538-2490

WEATHER DATA SOURCES: ASOS 121.425 (530) 533-5792.

COMMUNICATIONS: CTAF/UNICOM 122.8

® **NORCAL APP/DEP CON** 125.4

CLEARANCE DELIVERY PHONE: For CD ctc NorCal Apch at 916-361-6874.

RADIO AIDS TO NAVIGATION: NOTAM FILE MYV.

MARYSVILLE (VL) (DL) VOR/DME 110.8 MYV Chan 45 N39°05.92' W121°34.38' 338° 23.4 NM to fld. 62/16E.

VOR unusable:

013°-089° byd 25 NM

015°-089° byd 25 NM

184°-194° byd 25 NM

199°-225° byd 25 NM

207°-217° byd 25 NM

260°-301° byd 58 NM

275°-295° byd 28 NM blo 6,000'

297°-300° byd 25 NM

DME unusable:

275°-295° byd 28 NM blo 6,000'

