

WILLOWS/GLENN CO (WLW)(KWLW) 1 W UTC-8(-7DT) N39°30.95' W122°13.04'

SAN FRANCISCO

141 B NOTAM FILE RIU


L-2G

RWY 16-34: H4125X100 (ASPH) S-38, D-53 MIRL

IAP

RWY 16: Road. Rgt tfc.**RWY 34:** VASI(V4L)—GA 3.0° TCH 31'.**RWY 13-31:** H3788X60 (ASPH) S-12**RWY 13:** Trees. Rgt tfc.**RWY 31:** Thld dsplcd 243'.**SERVICE:** FUEL 100LL LGT ACTIVATE MIRL Rwy 16-34 and VASI Rwy 34—CTAF.**AIRPORT REMARKS:** Attended 1530-2330Z†. Fuel 24 hr card lock.**AIRPORT MANAGER:** 530-934-6530**COMMUNICATIONS:** CTAF/UNICOM 122.8

® OAKLAND CENTER APP/DEP CON 132.2

CLEARANCE DELIVERY PHONE: For CD ctc Oakland ARTCC at 510-745-3380.
WOODLAKE (O42) 2 S UTC-8(-7DT) N36°23.93' W119°06.41'

SAN FRANCISCO

425 B TPA-1225(800) NOTAM FILE RIU

RWY 07-25: H2203X50 (ASPH-TRTD)**RWY 07:** Trees.**RWY 25:** Bldg.**SERVICE:** FUEL 100LL**AIRPORT REMARKS:** Unattended. Arpt not approved for ngt use. Gross pavement strength provided by arpt manager, 8000 lbs.**AIRPORT MANAGER:** 559-564-8055**COMMUNICATIONS:** CTAF 122.9**CLEARANCE DELIVERY PHONE:** For CD ctc Oakland ARTCC at 510-745-3380.