

LONGMONT**VANCE BRAND** (LMO)(KLMO) 3 SW UTC-7(-6DT) N40°09.86' W105°09.82'**CHEYENNE**

5055 B NOTAM FILE DEN

L-10F, A

RWY 11-29: H4799X75 (CONC) S-30 MIRL 0.5% up NW

IAP

RWY 11: VASI(V2L)—GA 3.0° TCH 24'. Tree.**RWY 29:** VASI(V2L)—GA 3.0° TCH 35'. Road.**SERVICE:** S4 FUEL 100LL, JET A, MOGAS LGT ACTIVATE MIRL Rwy 11-29 and VASI Rwy 11 and Rwy 29—CTAF. Rwy 11 VASI unusable byd 3.9 NM. VASI does not provide obst clnc byd 3.9 NM from thld.**NOISE:** Noise abatement procedures in effect ctc arpt manager 303-651-8431.**AIRPORT REMARKS:** Attended dalgt hrs. Parachute jumping on and invof arpt primarily of rwy, avoid overflights mid fld. Ultralight and helicopter activity on and invof arpt. Rwy 29 has +15' highway 702' from thld, +25' to 35' bldgs/tanks aprx 1300' left of thld. NOTE: See Special Notices—Aerobatic Operations in Colorado, USAF 306 FTG Flight Training Areas, Vicinity of Colorado Springs and Pueblo Colorado.**AIRPORT MANAGER:** 303-651-8431**WEATHER DATA SOURCES:** AWOS-3 120.0 (303) 684-7545.**COMMUNICATIONS:** CTAF/UNICOM 122.975® **DENVER APP/DEP CON** 125.125**CLEARANCE DELIVERY PHONE:** For CD ctc Denver Apch at 303-342-1916.**RADIO AIDS TO NAVIGATION:** NOTAM FILE BJC.**JEFFCO (VH) (DH) VORW/DME** 115.4 BJC Chan 101 N39°54.78' W105°08.34' 345° 15.1 NM to fld. 5737/11E.

VOR unusable:

180°-225° byd 40 NM

226°-245° byd 36 NM blo 17,000'


246°-278° byd 30 NM blo 19,000'

279°-300° byd 34 NM blo 18,000'

301°-335° byd 40 NM

DME unusable:

246°-278° byd 30 NM

**MC ELROY AIRFIELD** (See KREMMLING on page 357)**MEADOW LAKE** (See COLORADO SPRINGS on page 333)