

YAMPA VALLEY (See HAYDEN on page 354)**YUMA MUNI** (2V6) 1 SE UTC-7(-6DT) N40°06.34' W102°42.87'

4138 B NOTAM FILE DEN

Rwy 16-34: H4201X75 (ASPH) S-12.5 MIRL**Rwy 16:** REIL. PAPI(P2L)—GA 3.0° TCH 39'. Tree.**Rwy 34:** REIL. PAPI(P2L)—GA 3.0° TCH 39'. Rgt tfc.**Rwy 12-30:** H3277X60 (ASPH-GRVL) 0.6% up NW**Rwy 12:** Road. Rgt tfc.**Rwy 30:** Road.**SERVICE:** **FUEL** 100LL, J **LGT** MIRL Rwy 16-34 preset med ints dusk-dawn. ACTVT REIL Rwy 16 and Rwy 34—CTAF. PCL not available for PAPI sys. Rwy 16 PAPI unusbl byd 8 deg right of cntrln.**AIRPORT REMARKS:** Attended Mon-Sat dalgt hrs. Fuel self serve. Be alert, intensive USAF student training invof Colorado Springs and Pueblo. Rwy 12-30 soft when wet. Rwy 12-30 center 650 ft asph, rmndr grvl. Rwy 12 has +20' bldg 90' from thld, 213' right. Rwy 30 has 2 ft ditch at thld OB; 4 ft fence 50 ft from thld OB. Twys marked with blue and yellow reflectors. See Special Notices—USAF 306 FTG Flight Training Areas, Vicinity of Colorado Springs and Pueblo Colorado.**AIRPORT MANAGER:** 970-848-3878**WEATHER DATA SOURCES:** AWOS-3 135.375 (970) 848-3007.**COMMUNICATIONS:** CTAF/UNICOM 122.8® **DENVER CENTER APP/DEP CON** 133.95**CLEARANCE DELIVERY PHONE:** For CD ctc Denver ARTCC at 303-651-4257.**RADIO AIDS TO NAVIGATION:** NOTAM FILE AKO.**AKRON (VH) (H) VORW/DME** 114.4 AKO Chan 91 N40°09.33' W103°10.78' 085° 21.6 NM to fld. 4623/13E.

VOR unusable:

228°-232° byd 40 NM

CHEYENNE**L-10G****IAP**