

SHIPROCK AIRSTRIP (5V5) 5 S UTC-7(-6DT) N36°41.86' W108°42.06'

5273 B NOTAM FILE ABQ

DENVER
H-4K, L-8H

RWY 02-20: H5214X75 (ASPH) S-11 PCN 3 F/D/Y/T MIRL 0.9% up S

RWY 02: PAPI(P2L)—GA 3.0° TCH 45'. Pole.

RWY 20: PAPI(P2L)—GA 3.0° TCH 44'.

SERVICE: LGT ACTVT MIRL Rwy 02-20—CTAF.

AIRPORT REMARKS: Unattended. Rwy 02-20 ditch NW of rwy entire len. Parl Twy A: cond poor; unmkd; sfc cracks with grass and loose aggregate. Emerg and maint coord — 505-371-8354/505-908-7961.

AIRPORT MANAGER: (505) 728-2804

COMMUNICATIONS: CTAF 122.9

CLEARANCE DELIVERY PHONE: For CD ctc Denver ARTCC at 303-651-4257.

RADIO AIDS TO NAVIGATION: NOTAM FILE FMN.

RATTLESNAKE (VH) (H) VORTACW 115.3 RSK Chan 100 N36°44.90' W108°05.93' 250° 29.2 NM to fld.
5821/14E.

VOR unusable:

007°-017° byd 40 NM blo 18,000'

018°-041° byd 40 NM

042°-062° byd 40 NM blo 15,000'

042°-062° byd 63 NM blo 20,000'

063°-066° byd 40 NM

067°-077° byd 40 NM blo 14,000'

067°-077° byd 75 NM

078°-094° byd 40 NM

095°-105° byd 40 NM blo 18,000'

106°-119° byd 40 NM blo 11,500'

106°-119° byd 62 NM blo 12,500'

106°-119° byd 76 NM

120°-125° byd 40 NM

235°-255° byd 40 NM blo 12,000'

235°-255° byd 84 NM blo 28,000'

256°-274° byd 40 NM

275°-285° byd 40 NM blo 30,000'

286°-327° byd 40 NM

328°-338° byd 40 NM blo 15,000'

344°-356° byd 40 NM blo 16,300'

344°-356° byd 66 NM

357°-006° byd 40 NM

SIERRA BLANCA RGNL (See RUIDOSO on page 458)