

MARLETTE TOWNSHIP (77G) 1 SW UTC-5(-4DT) N43°18.71' W83°05.46'

DETROIT

895 B NOTAM FILE LAN

L-28J

RWY 10-28: H3795X75 (ASPH) MIRL

IAP

RWY 10: PAPI(P2R)—GA 3.0° TCH 44' . Tree.**RWY 28:** PAPI(P2L)—GA 3.0° TCH 45' . Tree.**RWY 01-19:** H3500X75 (ASPH) MIRL 0.7% up N**RWY 01:** PAPI(P2L)—GA 3.0° TCH 21' .**RWY 19:** PAPI(P2L)—GA 3.0° TCH 40' . Tree.**SERVICE:** FUEL 100LL LGT ACTIVATE PAPI Rwy 01, 10, 19 and 28;


MIRL Rwy 01-19 & Rwy 10-28—CTAF.

AIRPORT REMARKS: Unattended. Deer & lrg birds on & invof arpt. 100LL

avbl H24 self svc via credit card. Trml bldg acce: 5-3-2-1*.

AIRPORT MANAGER: 810-459-4674**COMMUNICATIONS:** CTAF/UNICOM 122.8

③ CLEVELAND CENTER APP/DEP CON 122.7

CLEARANCE DELIVERY PHONE: For CD ctc Cleveland ARTCC at 440-774-0224/0490.**RADIO AIDS TO NAVIGATION:** NOTAM FILE LAN.**PECK (H) TACAN** Chan 87 ECK (114.0) N43°15.35' W82°43.08' 289° 16.7 NM to fld. 810/7W.**MARQUETTE/SAWYER RGNL** (SAW)(KSAW) 17 S UTC-5(-4DT) N46°20.95' W87°23.78'

GREEN BAY

1205 B ARFF Index—See Remarks NOTAM FILE SAW MON Airport

H-2K, L-31A

RWY 01-19: H9072X150 (ASPH-GRVD) S-111, D-184, 2S-175, 2D/2D2-750 PCR 450 F/B/X/T

IAP, AD

HIRL

RWY 01: MALSR. PAPI(P4L)—GA 3.0° TCH 51' .**RWY 19:** REIL. PAPI(P4L)—GA 3.0° TCH 53' . 0.5% down.**RUNWAY DECLARED DISTANCE INFORMATION****RWY 01:** TORA-9072 TODA-9072 ASDA-9072 LDA-9072**RWY 19:** TORA-9072 TODA-9072 ASDA-9072 LDA-9072**SERVICE:** S4 FUEL 100LL, JET A OX 1, 2 LGT When twr clsd ACTIVATE MALSR Rwy 01; REIL Rwy 19; PAPI Rwy 01 and Rwy 19; HIRL Rwy 01-19—CTAF.**AIRPORT REMARKS:** Attended 1000-0100Z±. For svc aft hrs call amgr cell or 810-417-1860. FBO svc aft hrs contact 906-222-3062. Ficons unmon 0500-0930Z±. Birds and deer on and invof arpt. PAEW on arpt monitor 119.975 (CTAF). Class I, ARFF Index B. Air carrier ops are not authorized in excess of 15 minutes before or after scheduled arrival/dep times without prior coordination with arpt manager. Unscheduled air carrier operations with more than 30 passenger seats require 48 hour prior permission, call arpt manager 906-346-3308 or 906-364-0939. Index C ARFF avbl with 48 hr hour prior permission, call arpt manager 906-346-3308 or 906-364-0939. General aviation and charter acct parking avbl at general aviation terminal only, lctd SE corner of arpt. S half of air carrier terminal ramp not plowed Oct-Apr. Frequent snow removal ops in progress various times Oct-Apr. Monitor CTAF. North air carrier ramp entrance/exit clsd 15 Nov-15 Apr. Ramp fee may be waived with fuel purchase; for FBO svc aft hrs call 906-251-0723.**AIRPORT MANAGER:** 906-346-3308**WEATHER DATA SOURCES:** AWOS-3PT 118.375 (906) 346-5126.**COMMUNICATIONS:** CTAF 119.975 UNICOM 122.7

RCO 122.5 (GREEN BAY RADIO)

③ MINNEAPOLIS CENTER APP/DEP CON 119.1

TOWER 119.975 (1100-0300Z±) **GND CON** 121.65**CLEARANCE DELIVERY PHONE:** For CD when ATCT is clsd ctc FSS via rco, if una ctc Minneapolis ARTCC at 651-463-5588.**AIRSPACE:** CLASS D svc 1100-0300Z±; other times CLASS E.**RADIO AIDS TO NAVIGATION:** NOTAM FILE SAW.**SAWYER (VH) (H) VOR/DME** 117.1 SAW Chan 118 N46°21.54' W87°23.85' at fld. 1196/4W.

VOR unusable:

000°-015° byd 40 NM

025°-040° byd 40 NM

075°-085° byd 40 NM

135°-145° byd 40 NM

240°-260° byd 40 NM

275°-300° byd 40 NM

330°-090° byd 10 NM blo 8,000'

DME unusable:

250°-090° byd 30 NM blo 4,500'

ILS 110.1 I-SOU Rwy 01. Class IE. Autopilot cpd apch NA blw 1,360'. Unmonitored.

COMM/NAV/WEATHER REMARKS: No emergency frequencies at twr.