

ZEELAND

OTTAWA EXEC (Z98) 3 E UTC-5(-4DT) N42°49.03' W85°55.68'

756 NOTAM FILE LAN

RWY 02-20: H3800X60 (ASPH) LIRL UP 1.1% N

RWY 02: Thld dspcd 294'.

RWY 20: Thld dspcd 191'.

SERVICE: S4 FUEL 100LL, JET A+ LGT ACTVT LIRL Rwy
02-20—CTAF, 5 clicks on SS—SR.

AIRPORT REMARKS: Attended Mon-Sat 1300-2200Z±. 200 ft lgtd ant
aprxly 1900 ft NE of Rwy 20. Rwy slips up fm South to North. 4 clicks
on CTAF for wind, temp, and altm info.

AIRPORT MANAGER: 616-218-6236

COMMUNICATIONS: CTAF 122.9

Ⓡ **GREAT LAKES APP/DEP CON** 128.4 (1030-0500Z±)

Ⓡ **CHICAGO CENTER APP/DEP CON** 128.4 (0500-1030Z±)

CLEARANCE DELIVERY PHONE: For CD ctc Great Lakes Apch at
269-459-3344, when Apch clsd ctc Chicago ARTCC at
630-906-8921.

RADIO AIDS TO NAVIGATION: NOTAM FILE GRR.

VICTORY (VH) (H) VORW/DME 115.95 VIO Chan 106(Y)
N42°47.20' W85°29.82' 280° 19.1 NM to fld. 802/4W.

DME unmonitored.

DME unusable:

011°-314° byd 30 NM blo 3,000'

VOR unusable:

140°-150° byd 40 NM

255°-260° byd 40 NM blo 6,000'

255°-260° byd 56 NM

CHICAGO

L-281

IAP

