

CRANDON/STEVE CONWAY MUNI (Y55) 3 SW UTC-6(-5DT) N45°31.36' W88°55.71'

GREEN BAY

1650 B NOTAM FILE GRB

L-14J

RWY 12-30: H3550X75 (ASPH) S-12 MIRL 0.6% up NW

IAP

RWY 30: Trees.

RWY 01-19: 2742X100 (TURF) 0.4% up N

SERVICE: LGT MIRL Rwy 12-30 preset to low SS-SR, incr intst and ACTVT—CTAF.

AIRPORT REMARKS: Unattended. Occasional deer on and infov arpt. Rwy 01 mkd with yellow cones. Rwy 19 mkd with yellow cones. Rwy 12 markings faded. Rwy 30 markings faded.

AIRPORT MANAGER: 715-902-0188

COMMUNICATIONS: CTAF 122.9

® **MINNEAPOLIS CENTER APP/DEP CON** 133.65

CLEARANCE DELIVERY PHONE: For CD ctc Minneapolis ARTCC at 651-463-5588.

RADIO AIDS TO NAVIGATION: NOTAM FILE RHI.

RHINELANDER (VL) (DH) VOR/DME 115.05 RHI Chan 97(Y)


N45°38.03' W89°27.47' 104° 23.3 NM to fld. 1599/2E.

VOR unusable:

- 144°-150° byd 20 NM
- 144°-150° byd 6 NM blo 6,600'
- 190°-195° byd 40 NM blo 9,000'
- 196°-202° byd 40 NM
- 207°-210° byd 28 NM blo 6,600'
- 225°-234° byd 40 NM
- 245°-246° byd 49 NM
- 247°-248° byd 40 NM
- 303°-307° byd 49 NM
- 315°-322° byd 40 NM

DME unusable:

- 180°-195° byd 25 NM



CRIVITZ MUNI (3D1) 3 SW UTC-6(-5DT) N45°12.88' W88°04.40'

GREEN BAY

735 B NOTAM FILE GRB

RWY 09-27: 2545X80 (TURF) 0.3% up W

RWY 09: Thld dsplcd 595'. P-line.

RWY 27: Thld dsplcd 138'. Trees.

RWY 18-36: H2164X60 (ASPH) S-12 LIRL

RWY 18: Thld dsplcd 115'. Road.

RWY 36: Thld dsplcd 101'. Road.

SERVICE: LGT ACTIVATE LIRL 18-36—123.0. Rotating bcn-5 clicks on—123.0.

AIRPORT REMARKS: Unattended. Deer on and infov arpt. Rwy 09-27 not plowed for winter months. Rwy 18-36 to confirm snow removal ctc arpt manager. Rwy end 09 mkd with yellow cones. Rwy end 27 mkd with yellow cones.

AIRPORT MANAGER: (715) 927-2793

COMMUNICATIONS: CTAF/UNICOM 122.8

CLEARANCE DELIVERY PHONE: For CD ctc Minneapolis ARTCC at 651-463-5588.