

HILL CITY MUNI (HLC)(KHLG) 1 NE UTC-6(-5DT) N39°22.81' W99°49.89'

2238 B TPA—3038(800) NOTAM FILE HLC

RWY 18-36: H5001X75 (CONC) S-12.5, D-16 PCN 8 R/C/X/U

HIRL 1.0% up N

RWY 18: REIL. PAPI(P4L)—GA 3.0° TCH 46'.

RWY 36: REIL. PAPI(P4L)—GA 3.0° TCH 33'. Road.

SERVICE: FUEL 100LL, JET A+ LGT ACTVT REIL Rwy 18 and Rwy 36; PAPI Rwy 18 and Rwy 36; HIRL Rwy 18-36—CTAF.

AIRPORT REMARKS: Attended on call. 24 hr attendant 785-421-5613. Self svc fuel. Agricultural acct opr vicinity of arpt dalgt hrs.

AIRPORT MANAGER: 785-769-3400

WEATHER DATA SOURCES: ASOS 118.425 (785) 421-3471.

COMMUNICATIONS: CTAF 122.9

RCO 122.3 (WICHITA RADIO)

Ⓡ DENVER CENTER APP/DEP CON 132.7

CLEARANCE DELIVERY PHONE: For CD if una to ctc on FSS freq, ctc Denver ARTCC at 303-651-4257.

RADIO AIDS TO NAVIGATION: NOTAM FILE HLC.

(VH) (H) VORTACW 113.7 HLC Chan 84 N39°15.52'

W100°13.55' O60° 19.8 NM to fld. 2690/8E.

VOR unusable:

271°-274° byd 40 NM


279°-289° byd 40 NM blo 4,800'

279°-289° byd 47 NM

WICHITA

H-5B, L-10H

IAP



HILLSBORO

ALFRED SCHROEDER FLD (M66) 0 SW UTC-6(-5DT) N38°20.49' W97°12.83'

1434 B NOTAM FILE ICT

RWY 17-35: H3229X44 (ASPH) LIRL 0.6% up N

RWY 17: PAPI(P4L)—GA 3.75° TCH 39'. Road.

RWY 35: PAPI(P4L)—GA 3.75° TCH 39'. Trees.

SERVICE: FUEL 100LL LGT ACTVT PAPI Rwy 17 and Rwy 35, LIRL Rwy 17-35—CTAF.

AIRPORT REMARKS: Unattended. 100LL fuel avbl 24 hrs self serve.

Ultralight activity invof arpt. Phone avbl 24 hrs in pilot lounge; 620-416-6102.

AIRPORT MANAGER: 620-947-3162

COMMUNICATIONS: CTAF 122.9

CLEARANCE DELIVERY PHONE: For CD ctc Wichita Apch at 316-350-1520.

RADIO AIDS TO NAVIGATION: NOTAM FILE SLN.

SALINA (VH) (H) VORTACW 117.1 SLN Chan 118 N38°55.51'

W97°37.28' 144° 39.9 NM to fld. 1316/7E.

VOR unusable:

017°-026° byd 40 NM

315°-016° byd 15 NM blo 6,000'

DME unusable:


300°-042° byd 15 NM blo 6,000'

• • • • •
HELIPAD H1: H40X40 (CONC)

HELIPAD H1: Bldg.

WICHITA

L-10I



HILLSIDE (See STILWELL on page 138)