
PLATTE MUNI (1D3) 1 NE UTC-6(-5DT) N43°24.28' W98°49.83'

OMAHA
L-12H

1618 B NOTAM FILE HON

RWY 14-32: H3100X60 (CONC) S-125 MIRL 0.5% up SE**RWY 14:** PAPI(P2L). Tree.**RWY 32:** PAPI(P2L). Trees. Rgt tfc.**SERVICE:** FUEL 100LL LGT ACTIVATE MIRL Rwy 14-32—CTAF.**AIRPORT REMARKS:** Attended Mon-Sat 1400-2300Z±. Fuel avbl 24 hrs with credit card. During winter months rwy could be slippery, confirm winter conditions with arpt manager call 605-337-2334/3923. Deer and other wildlife on and invof arpt.**AIRPORT MANAGER:** 605-337-3921**COMMUNICATIONS:** CTAF/AUNICOM 122.8

GCO 121.725 (4 clicks to MINNEAPOLIS CENTER and 6 clicks to FLIGHT SERVICES)

CLEARANCE DELIVERY PHONE: For CD if una via GCO ctc Minneapolis ARTCC at 651-463-5588.**RADIO AIDS TO NAVIGATION:** NOTAM FILE MHE.**MITCHELL (VL) (L) VORW/DME** 114.15 MHE Chan 88(Y) N43°46.62' W98°02.25' 233° 41.2 NM to fld.
1298/4E.

VOR unusable:

059°-075° byd 70 NM

165°-175° byd 40 NM

183°-213° byd 40 NM

211°-228° byd 40 NM

231°-271° byd 40 NM

DME unusable:

178°-188° byd 40 NM

205°-217° byd 40 NM

PRESHO MUNI (5P5) 1 E UTC-6(-5DT) N43°54.36' W100°02.20'

OMAHA

1760 B NOTAM FILE HON

RWY 10-28: 3350X150 (TURF-GRVL) LIRL 0.4% up W**RWY 10:** Road.**RWY 28:** Fence.**SERVICE:** LGT ACTIVATE LIRL Rwy 10-28—CTAF.**AIRPORT REMARKS:** Unattended. Wildlife and waterfowl on and invof arpt. Rwy 10-28 center 52' gravel plus gravel turnarounds. Rwy 10-28 marked with black and white cones.**AIRPORT MANAGER:** 605-280-4641**COMMUNICATIONS:** CTAF 122.9**CLEARANCE DELIVERY PHONE:** For CD ctc Minneapolis ARTCC at 651-463-5588.