

**HAVERSTRAW HELIPORT** (H43) 1 E UTC-5(-4DT) N41°12.66' W73°58.19'

NEW YORK

12 NOTAM FILE ISP

**HELIPAD H1:** H50X50 (ASPH)

**HELIPAD H1:** Bldg.

**SERVICE:** FUEL JET A LGT For lgts call 914-429-1200.

**NOISE:** Noise abatement; avoid residential area west of heliport.

**HELIPORT REMARKS:** Attended 1200-0000Z. For svc after hrs call 212-883-0999. Helipad H1 350' twrs 800' north of helipad. H1 Indg sfc is uneven & no mrkgs. Helicopters descend to point on turf area W of pavement and taxi to paved location. No mrkgs on pad and uneven pavement conds.

**AIRPORT MANAGER:** 845-429-1200

**COMMUNICATIONS:** CTAF/UNICOM 123.05

**CLEARANCE DELIVERY PHONE:** For CD ctc New York Apch at 516-683-2849.

**HEBER AIRPARK** (See GANSEVOORT on page 206)

**HOLLANDS INTL FLD** (See NEWFANE on page 231)

**HORNELL MUNI** (HTF)(KHTF) 3 N UTC-5(-4DT) N42°22.93' W77°40.93'

DETROIT

1219 B TPA—See Remarks NOTAM FILE BUF

H-10H, 11C, 12J, L-30I, 31E, 32F

**RWY 18-36:** H5000X75 (ASPH-GRVD) MIRL 0.5% up N

IAP

**RWY 18:** REIL. Thld dsplcd 500'. Hill.

**RWY 36:** REIL. PAPI(P4L)—GA 3.0° TCH 50'. Trees.

**SERVICE:** FUEL 100LL, JET A LGT ACTIVATE REIL Rwy 18-36 and MIRL Rwy 18-36—CTAF. REIL Rwy 18 OTS indef.

**AIRPORT REMARKS:** Attended 1300-2100Z. Frequent helicopter medivac ops, monitor CTAF. Rwy 36 PAPI unusable byd 5 degs right and left of centerline. TPA—2219(1000) daylight, 2419(1200) night. Cold temperature airport. Altitude correction required at or below -18C.

**AIRPORT MANAGER:** 607-968-9624

**WEATHER DATA SOURCES:** AWOS-3 118.475 (607) 324-9138.

**COMMUNICATIONS:** CTAF/UNICOM 122.7

**CLEVELAND CENTER APP/DEP CON** 124.325 or ctc Cleveland ARTCC at 440-774-0227.

**CLEARANCE DELIVERY PHONE:** For CD ctc Cleveland ARTCC at 440-774-0227.

**RADIO AIDS TO NAVIGATION:** NOTAM FILE ELZ.

**WELLSVILLE (DH) DME** 115.85 ELZ Chan 105(Y) N42°05.38' W77°59.97' 039° 22.5 NM to fld. 2298.

DME unusable:

170°-195° byd 25 NM

