

CUT BANK INTL (CTB)(KCTB) 3 SW UTC-7(-6DT) N48°36.50' W112°22.57'

3858 B AOE NOTAM FILE CTB MON Airport

RWY 05-23: H5300X75 (ASPH) S-27.5, D-37.5 PCN 10 F/D/Y/U

MIRL 0.3% up SW

RWY 23: PAPI(P2L)—GA 3.0° TCH 39'.

RWY 14-32: H5300X75 (ASPH) S-27.5, D-37.5 PCN 10 F/D/Y/U

MIRL 0.3% up NW

RWY 32: REIL. VASI(V4L)—GA 3.0° TCH 42'.

SERVICE: FUEL 100LL, JET A, A+ LGT ACTVT MIRL Rwy 05-23 and Rwy 14-32; REIL Rwy 32—CTAF. PAPI Rwy 23; VASI Rwy 32 opr consly.

AIRPORT REMARKS: Attended 1530-0030Z†. For fuel aft hrs call 406-873-8683 or 406-849-4245 cell. 24 hr cstms avbl on call-out 406-335-9610 ext 314. Cold temperature airport. Altitude correction required at or below -28C. Flight Notification Service (ADCUS) avbl.

AIRPORT MANAGER: 406-873-8683

WEATHER DATA SOURCES: ASOS 119.025 (406) 873-2939. Opr full-time 0700-0659Z†.

COMMUNICATIONS: CTAF/UNICOM 123.0

RCO 122.2 (GREAT FALLS RADIO)

® SALT LAKE CENTER APP/DEP CON 133.4

CLEARANCE DELIVERY PHONE: For CD if una to ctc on FSS freq, ctc Salt Lake ARTCC at 801-320-2568.

AIRSPACE: CLASS E.

RADIO AIDS TO NAVIGATION: NOTAM FILE CTB.

(VL) (DH) VORW/DME 113.35 CTB Chan 80(Y) N48°33.90' W112°20.60' 316° 2.9 NM to fld. 3791/17E.

VOR unusable:

049°-053° byd 40 NM

061°-073° byd 40 NM

079°-090° byd 40 NM

125°-130° byd 40 NM

143°-149° byd 40 NM

167°-177° byd 40 NM blo 9,000'

167°-177° byd 54 NM


178°-190° byd 40 NM

191°-201° byd 40 NM blo 12,000'

191°-201° byd 53 NM

202°-260° byd 40 NM

271°-282° byd 40 NM



GREAT FALLS

H-1D, L-13C

IAP

DAWSON COMMUNITY (See GLENDIVE on page 116)