
CRESCENT LAKE STATE (5S2) 2 NE UTC-8(-7DT) N43°31.97' W121°57.02'

KLAMATH FALLS

4820 NOTAM FILE MMV

L-1A

RWY 13-31: H3608X40 (ASPH) 1.3% up NW**RWY 13:** Trees.**RWY 31:** Trees.**AIRPORT REMARKS:** Unattended. Arpt CLOSED Nov 1-May 1 due to snow. Owner advises ctc with State Department of Aviation 503-378-4880. Grvl occasionally on rwy due to runoff. Sfc conds not rprtd.**AIRPORT MANAGER:** 503-378-2523**COMMUNICATIONS: CTAF** 122.9**CLEARANCE DELIVERY PHONE:** For CD ctc Seattle ARTCC at 253-351-3694.**RADIO AIDS TO NAVIGATION:** NOTAM FILE RDM.**DESCHUTES (VH) (H) VORTACW** 117.6 DSD Chan 123 N44°15.17' W121°18.21' 195° 51.5 NM to fld.
4103/18E.

VOR unusable:

013°-023° byd 40 NM

034°-039° byd 40 NM

108°-119° byd 40 NM

125°-135° byd 40 NM

150°-163° byd 40 NM

188°-201° byd 40 NM blo 10,500'

188°-201° byd 69 NM

202°-219° byd 40 NM

220°-240° byd 30 NM

241°-252° byd 40 NM blo 13,000'

241°-252° byd 47 NM

253°-257° byd 40 NM

258°-268° byd 40 NM blo 10,000'

258°-268° byd 48 NM

280°-286° byd 40 NM

289°-305° byd 40 NM blo 12,500'

289°-305° byd 48 NM

326°-338° byd 40 NM

TACAN AZIMUTH unusable:

220°-240° byd 30 NM

DME unusable:

220°-240° byd 30 NM