

OAKRIDGE STATE (5SØ) 1 W UTC-8(-7DT) N43°45.15' W122°30.27'

KLAMATH FALLS

1393 NOTAM FILE MMV

L-1A

RWY 09-27: H3610X47 (ASPH) 0.7% up W

RWY 09: Tree.

RWY 27: Road.

AIRPORT REMARKS: Unattended. Surface conditions not reported. Irregular winter maintenance, arpt may be clsd by snow. US Forest Service helicopters active in/ov arpt during fire season. Deer and elk on and in/ov arpt. Numerous areas of unsealed longitudinal and transverse cracking along full length of runway.

AIRPORT MANAGER: 503-378-4880

COMMUNICATIONS: CTAF 122.9

CLEARANCE DELIVERY PHONE: For CD ctc Seattle ARTCC at 253-351-3694.

RADIO AIDS TO NAVIGATION: NOTAM FILE EUG.

EUGENE (VH) (H) VORTACW 112.9 EUG Chan 76 N44°07.25' W123°13.37' 110° 38.2 NM to fid. 364/15E.

TACAN AZIMUTH unusable:

035°-055° byd 25 NM blo 9,400'

055°-075° byd 25 NM blo 9,000'

225°-230° byd 35 NM blo 5,500'

255°-295° byd 35 NM blo 7,500'

VOR unusable:

023°-033° byd 40 NM blo 18,000'

034°-040° byd 40 NM

120°-129° byd 40 NM

130°-140° byd 40 NM blo 8,000'

130°-140° byd 55 NM blo 11,000'

130°-140° byd 72 NM

141°-147° byd 40 NM

157°-166° byd 40 NM

167°-177° byd 40 NM blo 7,000'

167°-177° byd 62 NM

178°-204° byd 40 NM

205°-215° byd 40 NM blo 8,000'


205°-215° byd 64 NM

216°-286° byd 40 NM

287°-297° byd 40 NM blo 8,000'

287°-297° byd 51 NM

298°-320° byd 40 NM



ONTARIO

LARK'S LDG SPB (L49) 5 NNE UTC-7(-6DT) N44°05.58' W116°57.14'

KLAMATH FALLS

2160 NOTAM FILE MMV Not insp.

WATERWAY 07-25: 5600X200 (WATER)

WATERWAY 25: Rgt tfc.

AIRPORT MANAGER: 808-343-0599