

## CLE ELUM

**CLE ELUM MUNI** (S93) 1 E UTC-8(-7DT) N47°11.65' W120°53.04' SEATTLE  
 1945 B NOTAM FILE SEA  
**RWY 07-25:** H2379X60 (ASPH) MIRL 0.3% up W  
**RWY 07:** REIL. PAPI(P2L)—GA 4.0° TCH 20'. Rgt tfc.  
**RWY 25:** REIL. PAPI(P2L)—GA 4.0° TCH 20'.  
**SERVICE:** LGT ACTVT REIL Rwy 07 and 25; MIRL Rwy 07-25—CTAF. PAPI Rwy 07 and 25 oper cons. ACTVT rotg bcn—CTAF.  
**AIRPORT REMARKS:** Unattended. Wildlife on and invof rwy. Ditch 75' ft fm cntrln runs len of northside of rwy. Rwy 07-25 markings are faded.  
**AIRPORT MANAGER:** 509-674-2262  
**COMMUNICATIONS:** CTAF 122.9  
**CLEARANCE DELIVERY PHONE:** For CD ctc Seattle ARTCC at 253-351-3694.  
**COMM/NAV/WEATHER REMARKS:** Gliders use CTAF freq 122.3.

**DE VERE FLD** (2W1) 3 E UTC-8(-7DT) N47°10.65' W120°51.16' SEATTLE  
 1800 NOTAM FILE SEA  
**RWY 08-26:** H2055X30 (ASPH)  
**RWY 08:** Trees. Rgt tfc.  
**RWY 26:** Trees.  
**AIRPORT REMARKS:** Attended dalgt hrs. Fld occasionally CLOSED in winter. Wildlife on and invof rwy. Rwy 08-26 has 2 inch dropoff along entr rwy both sides. Rwy 08-26 svr unsealed cracks and joints. Rwy 08-26 NSTD mrkgs no nrs, small and square aiming points painted on rwy ends. All patterns to the south. Rwy 08-26 mrkgs faded.  
**AIRPORT MANAGER:** 509-962-2066  
**COMMUNICATIONS:** CTAF 122.9  
**CLEARANCE DELIVERY PHONE:** For CD ctc Seattle ARTCC at 253-351-3694.

## COLFAX

**LOWER GRANITE STATE** (ØØW) 12 S UTC-8(-7DT) N46°40.37' W117°26.50' SEATTLE  
 719 NOTAM FILE SEA  
**RWY 14-32:** 3400X50 (GRVL) 0.9% up SE  
**RWY 14:** Trees.  
**RWY 32:** Hill.  
**AIRPORT REMARKS:** Unattended. Vehicles; pedestrians, and animals on and invof rwy. No winter snow removal ops. Grv portions of rwy sfc rough and soft. Steep drop off on both sides of runway.  
**AIRPORT MANAGER:** (360) 618-2477  
**COMMUNICATIONS:** CTAF 122.9  
**CLEARANCE DELIVERY PHONE:** For CD ctc Seattle ARTCC at 253-351-3694.

**PORT OF WHITMAN BUSINESS AIR CENTER** (S94) 3 SW UTC-8(-7DT) N46°51.52' W117°24.84' SEATTLE  
 2181 B TPA—3010(829) NOTAM FILE SEA L-13B  
**RWY 08-26:** H3209X60 (ASPH) S-17 MIRL 1.0% up E  
**RWY 08:** Thld dsplcd 492'. Road.  
**RWY 26:** Thld dsplcd 450'. Hill.  
**RUNWAY DECLARED DISTANCE INFORMATION**  
**RWY 08:** TORA-3209 TODA-3209 ASDA-3209 LDA-2718  
**RWY 26:** TORA-3209 TODA-3209 ASDA-3209 LDA-2890  
**SERVICE:** LGT ACTIVATE MIRL Rwy 08-26—CTAF.  
**AIRPORT REMARKS:** Attended Jan-Dec 1600-0000Z. Deer invof rwy. Watch for birds invof creek south of arpt. Rwy 08-26 farm machinery may be opr in flds on both sides of rwy and off both rwy ends. 30' bldg 250' south AER 26. Dense agricultural ops Feb-Oct.  
**AIRPORT MANAGER:** 509-397-2061  
**COMMUNICATIONS:** CTAF/UNICOM 122.8  
**CLEARANCE DELIVERY PHONE:** For CD ctc Seattle ARTCC at 253-351-3694.  
**RADIO AIDS TO NAVIGATION:** NOTAM FILE PUW.  
**PULLMAN (VL) (L) VORW/DME** 117.15 PUW Chan 118(Y) N46°40.45' W117°13.41' 305° 13.6 NM to fld.  
 2772/20E. DME unmonitored.  
 DME unusable:  
 040°-045° byd 35 NM blo 8,000'  
 065°-070° byd 30 NM blo 7,000'  
 090°-095° byd 35 NM blo 7,000'  
 VOR unusable:  
 032°-100° byd 40 NM  
 155°-195° byd 40 NM