

LAURIER

AVEY FLD (69S) 2 SW UTC-8(-7DT) N48°59.90' W118°13.36' SEATTLE
 1655 LRA NOTAM FILE SEA
RWY 17-35: 1975X40 (GRVL)
RWY 17: Trees.
RWY 35: Trees.
AIRPORT REMARKS: Unattended. Vehicles and animals on and invof rwy. Rwy 17 marked with retro-reflective devices. Bldg in pri sfc, slip both sides of rwy, and steep drop off at rwy ends. Helicopter operations on airport during fire season. Shoulders very soft and rough both sides of rwy. Canadian and U.S. customs avbl on hwy to the west. U.S. based acft should park on the U.S. side of ramp, south, and Canadian based acft should park on north side of ramp.
AIRPORT MANAGER: 509-631-0623
COMMUNICATIONS: CTAF 122.9
CLEARANCE DELIVERY PHONE: For CD ctc Seattle ARTCC at 253-351-3694.

LEAVENWORTH

LAKE WENATCHEE STATE (27W) 14 NW UTC-8(-7DT) N47°49.16' W120°43.19' SEATTLE
 1939 NOTAM FILE SEA
RWY 09-27: 2473X100 (TURF) 0.4% up W
RWY 09: Road.
RWY 27: Road.
AIRPORT REMARKS: Unattended. Arpt CLOSED 1 Oct-1 Jun. Pedestrians; vehicles and animals on and invof rwy. Rwy marked with reflectors during dates airport is open.
AIRPORT MANAGER: 360-618-2477
COMMUNICATIONS: CTAF 122.9

LIND (ØSØ) 2 NE UTC-8(-7DT) N46°58.61' W118°35.23' SEATTLE
 1507 B NOTAM FILE SEA
RWY 05-23: H3197X50 (ASPH) HIRL L-13A
RWY 23: Hiil.
SERVICE: LGT ACTIVATE HIRL Rwy 05-23-CTAF.
AIRPORT REMARKS: Unattended. East end of rwy has 800' by 50' dirt graded safety area. Rwy 05-23 markings faded.
AIRPORT MANAGER: 509-677-3241
COMMUNICATIONS: CTAF 122.9
CLEARANCE DELIVERY PHONE: For CD ctc Grant County Apch at 509-762-2842, when Apch clsd ctc Seattle ARTCC at 253-351-3694.
RADIO AIDS TO NAVIGATION: NOTAM FILE MWH.
MOSES LAKE (VH) (DH) VORW/DME 115.0 MWH Chan 97 N47°12.65' W119°19.01' 097° 33.0 NM to fld. 1193/18E.
 VOR unusable:
 025°-040° byd 40 NM
 055°-070° byd 40 NM
 071°-081° byd 40 NM blo 28,000'
 175°-198° byd 40 NM blo 6,000'
 175°-198° byd 67 NM blo 10,000'
 175°-198° byd 70 NM
 200°-210° byd 40 NM
 220°-230° byd 40 NM
 240°-253° byd 40 NM blo 18,000'
 254°-260° byd 40 NM
 315°-345° byd 40 NM

LITTLE GOOSE LOCK AND DAM (See STARBUCK on page 278)

LOPEZ

FISHERMANS BAY SPB (81W) 1 N UTC-8(-7DT) N48°30.99' W122°55.08' SEATTLE
 00 NOTAM FILE SEA
WATERWAY 05W-23W: 3000X150 (WATER)
WATERWAY 05W: Rgt tfc.
SEAPLANE REMARKS: Unattended. Avoid overflights of houses on surrounding land. No step taxi in bay. Beware of boats anchored in seaplane ldg area.
AIRPORT MANAGER: 360-468-4116
COMMUNICATIONS: CTAF 122.9
CLEARANCE DELIVERY PHONE: For CD ctc Whidbey Apch at 360-257-3310.