

WASHINGTON
CONTINUED FROM PRECEDING PAGE

RADIO AIDS TO NAVIGATION: NOTAM FILE MWH.

MOSES LAKE (VH) (DH) VORW/DME 115.0 MWH Chan 97 N47°12.65' W119°19.01' at fld. 1193/18E.

VOR unusable:

025°-040° byd 40 NM
055°-070° byd 40 NM
071°-081° byd 40 NM blo 28,000'
175°-198° byd 40 NM blo 6,000'
175°-198° byd 67 NM blo 10,000'
175°-198° byd 70 NM
200°-210° byd 40 NM
220°-230° byd 40 NM
240°-253° byd 40 NM blo 18,000'
254°-260° byd 40 NM
315°-345° byd 40 NM

PELLY NDB (MHW/LOM) 408 MW N47°06.94' W119°16.47' 324° 5.9 NM to fld. 1136/18E.

ILS 109.5 I-MWH Rwy 32R. Class IB. LOM PELLY NDB. ILS and COMLO unmonitored when ATCT clsd.

• • • • •
HELIPAD H1: H50X50 (ASPH)

HELIPAD H2: H50X50 (ASPH)

MOSES LAKE MUNI (W2Ø) 2 NE UTC-8(-7DT) N47°08.52' W119°14.27'

SEATTLE

1203 B NOTAM FILE SEA

RWY 16-34: H2513X50 (ASPH) S-8 MIRL

RWY 16: PAPI(P2L)—GA 3.0°. Thld dsplcd 466'. Tree.

RWY 34: PAPI(P2L)—GA 3.0°. Thld dsplcd 253'. Bldg. Rgt tfc.

SERVICE: S4

AIRPORT REMARKS: Unattended. Bird haz. Pilots bring own ropes.

AIRPORT MANAGER: 509-764-3713

COMMUNICATIONS: CTAF/UNICOM 123.0

CLEARANCE DELIVERY PHONE: For CD ctc Grant County Apch at 509-762-2842, when Apch clsd ctc Seattle ARTCC at 253-351-3694.

MOSES LAKE N47°12.65' W119°19.01' NOTAM FILE MWH.

SEATTLE

(VH) (DH) VORW/DME 115.0 MWH Chan 97 at Grant Co Intl. 1193/18E.

H-1C, L-13A

VOR unusable:

025°-040° byd 40 NM
055°-070° byd 40 NM
071°-081° byd 40 NM blo 28,000'
175°-198° byd 40 NM blo 6,000'
175°-198° byd 67 NM blo 10,000'
175°-198° byd 70 NM
200°-210° byd 40 NM
220°-230° byd 40 NM
240°-253° byd 40 NM blo 18,000'
254°-260° byd 40 NM
315°-345° byd 40 NM

RCO 122.4 (SEATTLE RADIO)

MOUNT CONSTITUTION N48°40.79' W122°50.48'

SEATTLE

RCO 122.3 (SEATTLE RADIO)

L-1E