

ELK MOUNTAIN EHY N41°43.52' W106°27.57'/7299
AWOS-3 118.8 (307) 348-7320 Stand alone mountain top facility.

SALT LAKE CITY
H-3E, L-9D, 11D

EVANSTON—UINTA CO BURNS FLD (EVW)(KEVW) 3 W UTC-7(-6DT) N41°16.49' W111°02.08'

SALT LAKE CITY

7143 B NOTAM FILE EVW MON Airport

H-3E, L-9D, 11D

RWY 05-23: H7300X100 (ASPH-GRVD) S-73, D-93, 2D-148

IAP

PCR 295 F/D/X/T HIRL

RWY 05: REIL. PAPI(P4L)—GA 3.0° TCH 45'.

RWY 23: MALSR. PAPI(P4L)—GA 3.0° TCH 44'.

SERVICE: S4 FUEL 100LL, JET A OX 2 LGT ACTVT MALSR Rwy 23;

REIL Rwy 05; HIRL Rwy 05-23—CTAF. Rwy 05-23 PAPIs on continuously.

AIRPORT REMARKS: Attended 1400-0200Z†. For svc after hrs call 1-307-789-2256. Hangars only occasionally available, arpt changes facility fee.

AIRPORT MANAGER: 307-789-2256

WEATHER DATA SOURCES: ASOS 120.0 (307) 789-0585.

COMMUNICATIONS: CTAF/UNICOM 123.0

® SALT LAKE CENTER APP/DEP CON 127.7

GCO 121.72 (SALT LAKE CENTER CD) Casper FSS not avbl.

CLEARANCE DELIVERY PHONE: For CD if una via GCO ctc Salt Lake ARTCC at 801-320-2568.

RADIO AIDS TO NAVIGATION: NOTAM FILE EVW.

(VL) (DL) VORW/DME 109.6 EVW Chan 33 N41°16.35'

W111°02.81' at fld. 7145/13E.

VOR unusable:

020°-095° byd 40 NM

030°-046° byd 30 NM blo 14,000'

105°-180° byd 40 NM

215°-315° byd 40 NM

DME unusable:

030°-046° byd 30 NM blo 14,000'

ILS/DME 108.9 I-EVW Chan 26 Rwy 23. Class IE. Glideslope unusable byd 5° rgt of course. Status is not remotely Monitored.

