

**YAP ISLAND****YAP INTL** (T11)(PTYA) 0 SW UTC+10 N9°29.93' E138°04.95'

GNC 13

91 B NOTAM FILE HNL

P-1A

**RWY 07-25:** H6000X150 (ASPH-GRVD) S-75, D-160, 2D-230 MRL

IAP

**RWY 07:** REIL. PAPI(P4L)—GA 3.0° TCH 47'. Ground.**RWY 25:** REIL. PAPI(P4L)—GA 3.0° TCH 49'. Ground.**SERVICE:** FUEL JET A1 LGT ACTVT REILs 07 and 25; PAPI Rwy 07 and 25; MRL Rwy 07-25—123.6. Bcn OTS.**AIRPORT REMARKS:** Attended Mon-Fri 1730-0230Z, Sat on call, Sun on call. Sat 24 hr PPR with filed flt plan or phone (691)

350-2128 Fax (691) 350-2344. PPR for ldg to be filed 48 hr in advance with the Secretary of Transportation, Federated States of Micronesia, P.O. Box PS-2, Pohnpei, FSM 96941, phone 011(691)320-2865, fax 011-(691)320-2798.

Please see FSM DOTC&amp;I: Div. of Civil Aviation's website for procedures and forms used to request PPR into FSM;

<http://www.tci.gov.fm/civilaviation/forms.html>. Be alert when taxiing cracks on right and left side of twy.**AIRPORT MANAGER:** 691-350-2128**COMMUNICATIONS:** CTAF 123.6**YAP RADIO** 123.6 LAA. 5205X USB emerg only, 2182 emerg only.**RADIO AIDS TO NAVIGATION:** NOTAM FILE HNL.**NDB/DME (HW)** 317 YP Chan 122 N9°29.97' E138°05.31' at fld. 82/1E.

DME unusable:

001°-009° byd 10 NM

010°-035° byd 10 NM blo 12,000'

035°-075° byd 25 NM blo 4,000'

076°-105° byd 25 NM

280°-000° byd 25 NM blo 12,000'

**COMM/NAV/WEATHER REMARKS:** Chan 122 paired with VHF freq 117.5.