

**FRANCISCO C ADA/SAIPAN INTL** (GSN)(PGSN) 4 SW UTC+10 N15°07.21' E145°43.80' **GNC 7**  
 214 B TPA—See Remarks LRA ARFF Index—See Remarks NOTAM FILE GSN **P-1A**  
**RWY 07-25:** H8699X200 (ASPH-GRVD) S-87, D-175, 2D-350, 2D/2D2-690 PCR 715 F/A/X/T HIRL **IAP**  
**RWY 07:** MALS. REIL. Rgt tfc.  
**RWY 25:** REIL. PAPI(P4L)—GA 3.0° TCH 75' .  
**RWY 06-24:** H7001X100 (ASPH) PCN 67 R/A/X/T MIRL  
**RWY 06:** Thld dsplcd 396' .  
**RUNWAY DECLARED DISTANCE INFORMATION**  
**RWY 06:** TORA-7001 TODA-6800 ASDA-6645 LDA-6600  
**RWY 07:** TORA-8699 TODA-8669 ASDA-8664 LDA-8010  
**RWY 24:** TORA-6400 TODA-7001 ASDA-6302 LDA-7000  
**RWY 25:** TORA-8699 TODA-8699 ASDA-8045 LDA-8010  
**SERVICE:** FUEL 100, 100LL, JET A1+ LGT SS-SR.  
**AIRPORT REMARKS:** Attended continuously. PPR from Executive Director Commonwealth Ports Authority Saipan call (670) 237-6500 Mon-Fri 2200-0700Z other times call 670-237-6535. For Apt Security call (670) 237-6529. Immigration and Customs available during scheduled operations. Other times prior arrangements must be made with CBP port director call (670) 288-0025/26. Rwy 06-24 open for taxiing only (not avbl for lng and tkof). Open for ldg and tkof when Rwy 07-25 clsd. Class I, ARFF Index D. Clsd to unsked ACR opns with more than 30 psgr seats exc PPR call or write amgr 670-237-6500, P.O. Box 501055 Saipan MP 96950. TPA—Traffic pattern altitude for large and turbine powered acft 1700(1485), small aircraft 1200(985).  
**AIRPORT MANAGER:** 670-237-6500  
**WEATHER DATA SOURCES:** ASOS (670) 288-5565 SAWRS.  
**COMMUNICATIONS:** ATIS 127.2  
**GUAM CERAP APP/DEP CON 118.4**  
**TOWER 125.7 GND CON 121.8**  
**AIRSPACE:** CLASS D.  
**RADIO AIDS TO NAVIGATION:** NOTAM FILE HNL.  
**SAIPAN NDB (HW) 312 SN N15°06.69' E145°42.62' 293° 1.3 NM to fld. 83/2E.**  
**ILS/DME 109.9 I-GSN Chan 36 Rwy 07. Ry 07 VGS1 and glidepath not coincident. Glideslope unusable byd 9 NM.**

## TINIAN ISLAND

**FRANCISCO MANGLONA BORJA/TINIAN INTL** (TNI)(PGWT) 1 N UTC+10 N14°59.95' E145°37.16' **GNC 7**  
 270 B TPA—See Remarks Class I, ARFF Index A NOTAM FILE HNL **P-1A**  
**RWY 08-26:** H8600X151 (ASPH-CONC-GRVD) S-75, D-200, 2D-400, 2D/2D2-832 PCR 710 F/A/X/T MIRL **IAP**  
**RWY 08:** REIL. PAPI(P4L)—GA 2.98° TCH 43' . Hill.  
**RWY 26:** REIL. PAPI(P4L)—GA 2.99° TCH 45' . Rgt tfc.  
**RUNWAY DECLARED DISTANCE INFORMATION**  
**RWY 08:** TORA-8600 TODA-8600 ASDA-8600 LDA-8600  
**RWY 26:** TORA-8600 TODA-8600 ASDA-8600 LDA-8600  
**SERVICE:** LGT ACTVT REIL Rwy 08 and Rwy 26. MIRL Rwy 08-26 ctc arpt 1700-0500Z on CTAF 123.6. For emergencies between 0500-1700Z lgts can be requested by contacting Port Police (670) 433-9295/9294 or CTAF 123.6  
**AIRPORT REMARKS:** Attended 1700-0500Z, other times PPR from CPA Tinian manager, Tinian call 670-433-9296/94 Mon-Sun. PPR fm executive director Commonwealth Ports Authority Saipan, call 664-3500/01/02 Mon-Fri. Arpt CLOSED to unscheduled air carrier operations with more than 10 pax seats except 24 hrs PPR rqrd in writing to amgr. P.O. Box 235, Tinian MP 96952. Rdo deadzone on W end of Twy Alpha to Rwy 08. ARFF svc available 1700-0500Z and for air carrier ops with more than 9 passenger seats. Cust avbl dur sked ops. Otr times prior arrangements must be made with Customs Border Patrol Protection Saipan, call 288-0028. TPA—Traffic pattern altitude for large and turbine powered acft 1803(1532); small acft 1303(1032).  
**AIRPORT MANAGER:** (670) 433-9294  
**COMMUNICATIONS:** CTAF 123.6  
**RADIO AIDS TO NAVIGATION:** NOTAM FILE HNL.  
**SAIPAN NDB (HW) 312 SN N15°06.69' E145°42.62' 140° 8.5 NM to fld. 83/2E.**