

AMARILLO

BUFFALO (1E7) 9 S UTC-6(-5DT) N35°03.83' W101°52.66'

DALLAS-FT WORTH

3640 B NOTAM FILE FTW

RWY 02-20: 6200X150 (TURF) LIRL

RWY 02: Fence.

RWY 20: Tree. Rgt tfc.

RWY 08-26: 1600X102 (TURF) LIRL(NSTD)

RWY 08: P-line.

RWY 26: Road.

SERVICE: LGT Rwy 08-26 nstd solar LIRL.

AIRPORT REMARKS: Attended irregularly.

AIRPORT MANAGER: 720-412-1132

COMMUNICATIONS: CTAF/UNICOM 122.8

CLEARANCE DELIVERY PHONE: For CD ctc Albuquerque ARTCC at 505-856-4861.

PALO DURO (1E4) 3 S UTC-6(-5DT) N35°08.62' W101°50.35'

DALLAS-FT WORTH

3639 NOTAM FILE FTW

RWY 17-35: 3700X50 (TURF-GRVL)

RWY 17: P-line.

RWY 35: Fence.

AIRPORT REMARKS: Unattended. Arpt fenced, gates locked, no aces. Rwy not suitable for acft. Arpt hazardous for tsnts; rwy not mkd or defined; 63 ft mkd/ltgd transmission line acrs Rwy 17 end. Rwy 17-35 soft when wet on S end; loose grvl on rwy, vegetation on rwy.

AIRPORT MANAGER: 806-376-5853

COMMUNICATIONS: CTAF 122.9

CLEARANCE DELIVERY PHONE: For CD ctc Albuquerque ARTCC at 505-856-4861.

RICK HUSBAND AMARILLO INTL (AMA)(KAMA) 7 E UTC-6(-5DT) N35°13.16' W101°42.36'

DALLAS-FT WORTH

3607 B TPA—See Remarks LRA ARFF Index—See Remarks NOTAM FILE AMA

H-6G, L-15B

RWY 04-22: H13502X200 (CONC-GRVD) S-100, D-200, 2S-175, 2D-400 PCR 1820 R/D/W/T

IAP, AD

HIRL(NSTD)

RWY 04: MALSR. PAPI(P4L)—GA 3.0° TCH 61'. RVR-T

RWY 22: MALSR. PAPI(P4L)—GA 3.0° TCH 77'. RVR-R

RWY 13-31: H7901X150 (CONC-GRVD) S-100, D-200, 2S-175, 2D-400 PCR 780 R/D/W/T HIRL

RWY 13: REIL. PAPI(P4L)—GA 3.0° TCH 52'.

RWY 31: PAPI(P4L)—GA 3.0° TCH 52'.

RUNWAY DECLARED DISTANCE INFORMATION

RWY 04: TORA-13502 TODA-13502 ASDA-13502 LDA-13502

RWY 13: TORA-7901 TODA-7901 ASDA-7901 LDA-7901

RWY 22: TORA-13502 TODA-13502 ASDA-13502 LDA-13502

RWY 31: TORA-7901 TODA-7901 ASDA-7901 LDA-7901

SERVICE: S4 FUEL 100LL, JET A1+ OX 2, 4 LGT When ATCT clsd, to incr instst and ACTVT MALSR Rwys 04 and 22; REIL Rwy 13; HIRL Rwys 04-22, 13-31; all twys—CTAF.

AIRPORT REMARKS: Attended continuously. Tiltrotor acft activity invof arpt. Class I, ARFF Index B. Index C equip avbl upon req. TPA for propeller acft 4502 (895), turbojet acft 5002 (1395), overhead 5502 (1895). Rwy 04-22 center 130' grvd full length. RWY 04 RVR AVBL 1200-0600Z± CTC TWR. Rwy 04-22 NSTD HIRL due to spacing. HIRL 50 ft from rwy edge, NSTD dstc fm cntrln-pavement outside rwy edge stripes may not be full strength and depth perception problems may exist during periods of darkness. Flight Notification Service (ADCUS) available. Lndg fee.

AIRPORT MANAGER: 806-335-1671

WEATHER DATA SOURCES: ASOS 118.85 (806) 223-2973.

COMMUNICATIONS: CTAF 118.3 ATIS 118.85 UNICOM 122.95

AMARILLO RCO 122.3 (FORT WORTH RADIO) (0600-1200Z±)

Ⓡ APP/DEP CON 119.5 (1200-0600Z±)

Ⓡ ALBUQUERQUE CENTER APP/DEP CON 127.85 (0600-1200Z±)

TOWER 118.3 (1200-0600Z±) GND CON 121.9 CLNC DEL 121.65

CLEARANCE DELIVERY PHONE: For CD if una to ctc on FSS freq, ctc Albuquerque ARTCC at 505-856-4561.

AIRSPACE: CLASS C svc ctc APP CON svc 1200-0600Z±; other times CLASS E.

RADIO AIDS TO NAVIGATION: NOTAM FILE FTW.

PANHANDLE (H) (H) VORTACW 116.6 PNH Chan 113 N35°14.10' W101°41.94' at fld. 3595/8E.

PANDE NDB (LONW) 251 AM N35°08.79' W101°48.33' 040° 6.6 NM to fld. 3609/8E. NOTAM FILE AMA.

NDB unmonitored when ATCT clsd.

ILS 110.3 I-AMA Rwy 04. Class IB. LOM PANDE NDB. Unmonitored when ATCT clsd.

LDA/DME 111.1 I-RIQ Chan 48 Rwy 22. Autopilot coupled apchs NA blw 3,762'.

ASR (1200-0600Z±)