

FORT WORTH**BOURLAND FLD** (50F) 17 SW UTC-6(-5DT) N32°34.91' W97°35.45'

873 B NOTAM FILE FTW

RWY 17-35: H4049X60 (ASPH) RWY LGTS(NSTD) 0.9% up N**RWY 17:** VASI(V2L)—GA 3.0° TCH 23'. Thld dspcd 392'. Road.**RWY 35:** VASI(V2L)—GA 3.5° TCH 28'. Thld dspcd 215'. Trees.**SERVICE:** FUEL 100LL, JET A LGT ACTVT MIRL Rwy 17-35—CTAF.

Rwy 17-35 light spacing 100' between rwy lts.

AIRPORT REMARKS: Attended Mon-Sat dalgt hours. For svcs aft hrs call 817-752-4701. Deer and wildlife on and invof rwy. 100LL self serve. Arpt clsd to tsnt student tfc. Acft ovr 12,500 lb max GWT prohibited. Rwy 17 dthr lts and mkgs not coincident.**AIRPORT MANAGER:** 682-260-3778**COMMUNICATIONS:** CTAF/UNICOM 123.0® **LONE STAR APP/DEP CON** 135.975**CLEARANCE DELIVERY PHONE:** For CD ctc Lone Star Appch at 972-615-2799.**RADIO AIDS TO NAVIGATION:** NOTAM FILE FTW.**MILLSAP (VH) (H) VORTACW** 117.7 MQP Chan 124 N32°43.57' W97°59.85' 104° 22.3 NM to fld. 900/9E.

VOR unusable:

004°-009° byd 40 NM

010°-054° byd 40 NM blo 3,800'

010°-054° byd 46 NM blo 5,000'

010°-054° byd 56 NM

055°-066° byd 40 NM blo 3,800'

055°-066° byd 50 NM

230°-247° byd 40 NM

248°-258° byd 40 NM blo 3,700'

248°-258° byd 53 NM

259°-270° byd 40 NM blo 6,000'

259°-270° byd 63 NM

271°-285° byd 40 NM

312°-316° byd 40 NM

325°-340° byd 40 NM blo 3,000'

325°-340° byd 46 NM blo 5,000'

325°-340° byd 66 NM

353°-003° byd 40 NM blo 18,000'

DALLAS-FORT WORTH**COPTER****L-17C, A****IAP**