

MARLIN (T15) 3 NE UTC-6(-5DT) N31°20.44' W96°51.12'
 411 NOTAM FILE FTW
RWY 17-35: H3021X50 (ASPH) S-4
RWY 17: Trees.

RWY 35: Thld dspclcd 90'. Fence.

AIRPORT REMARKS: Unattended. Arprt day VFR only. No lights. Windsock may be unrel due to trees in proximity and mast not ver.

AIRPORT MANAGER: 254-275-0051

COMMUNICATIONS: CTAF 122.9

Ⓡ **WACO APP/DEP CON** 127.65 (1200-0600Z†)

Ⓡ **FORT WORTH CENTER APP/DEP CON** 133.3 (0600-1200Z†)

CLEARANCE DELIVERY PHONE: For CD etc Fort Worth ARTCC at 817-858-7584.

RADIO AIDS TO NAVIGATION: NOTAM FILE ACT.

WACO (VH) (H) VORTACW 115.3 ACT Chan 100 N31°39.73'
 W97°16.14' 123° 28.8 NM to fld. 507/9E.

VOR unusable:

125°-149° byd 40 NM
 149°-159° byd 47 NM
 159°-187° byd 40 NM
 188°-198° byd 40 NM blo 12,000'
 199°-234° byd 40 NM
 235°-245° byd 50 NM
 246°-256° byd 40 NM blo 18,000'
 246°-256° byd 52 NM
 257°-267° byd 58 NM
 268°-282° byd 51 NM
 270°-335° byd 35 NM blo 4,000'
 283°-293° byd 40 NM blo 6,000'
 283°-293° byd 58 NM
 294°-330° byd 40 NM

HOUSTON
L-19D, 21A
IAP

