

## SAN ANTONIO

**BOERNE STAGE AIRFIELD** (5C1) 20 NW UTC-6(-5DT) N29°43.39' W98°41.67'

SAN ANTONIO

1384 B NOTAM FILE SJT

L-19C

RWY 17-35: H5006X60 (ASPH) LIRL

IAP, AD

RWY 17: Thld dsplcd 629'. Fence. Rgt tfc.

RWY 35: Thld dsplcd 1086'. Trees.

SERVICE: S4 FUEL 100LL, JET A OX 4

NOISE: Noise abatement procedures in effect ctc AMGR. All ldg turbine acft must be stage 3 or better. No tgls, stop and go or low apchs.

AIRPORT REMARKS: Attended 1400-2300Z. Glider act on and invof arpt. Rwy 35, 35 ft lgtd pwr poles acrs apch. Use EXTREME CAUTION when oprg into and out of 5C1 for over flight tfc ldg San Antonio Intl (KSAT) at 3000 ft MSL and abv. See LTA-SAT-32. Landing fees in effect.

AIRPORT MANAGER: 337-258-8387

WEATHER DATA SOURCES: AWOS-3 118.725 (830) 755-9099.

COMMUNICATIONS: CTAF/UNICOM 123.0

④ SAN ANTONIO APP/DEP CON 125.1

CLEARANCE DELIVERY PHONE: For CD ctc San Antonio Apch at 210-805-5516.

RADIO AIDS TO NAVIGATION: NOTAM FILE SAT.

SAN ANTONIO (VH) (H) VORTACW 116.8 SAT Chan 115 N29°38.64' W98°27.68' 283° 13.1 NM to fld. 1159/8E.

VOR unusable:

018°-022° byd 40 NM

028°-032° byd 40 NM

342°-347° byd 40 NM

355°-002° byd 40 NM blo 18,000'

COMM/NAV/WEATHER REMARKS: UNICOM unmnt.

**BULVERDE AIRPARK** (1T8) 16 N UTC-6(-5DT) N29°44.36' W98°27.08'

SAN ANTONIO

1088 B NOTAM FILE SJT

L-19C

RWY 17-35: H2783X40 (ASPH) LIRL(NSTD)

RWY 17: Thld dsplcd 490'. P-line. Rgt tfc.

RWY 35: Thld dsplcd 200'. Trees.

SERVICE: S4 FUEL 100LL LGT ACTVT LIRL Rwy 17-35-CTAF. Rwy 17-35 NSTD LIRL; only cntr 2600 ft lgtd; Rwy 17 dsplcd thr has single green lgt each side. Rwy 35 has no dsplcd thr lgts. Arpt beacon dusk-0400Z.

NOISE: Noise abatement procs in efct ctc AMGR 830-438-4359 or 210-240-1365.

AIRPORT REMARKS: Attended 1500-2300Z. Deer on or invof arpt. Fuel avbl 24 hrs self svc with major credit card. Rwy 17 and Rwy 35 mkd with 20 ft high nrs; no cntrln stripes. Nrs not at dsplcd thr, no dsplcd thr markings. No touch and go, stop and go, or low apchs. All tfc right hand Rwy 17. Use extreme ctn for high per mil acft from Randolph AFB at or abv 3000 ft MSL Mon-Fri 1400-0400Z and when twr hrs extd by NOTAM, ocnl Sat and Sun. Hel experts adj ctc at 210-930-0125 or 210-501-3111. Hel skid ldg prohibited Rwy 17-35.

AIRPORT MANAGER: 210-275-4970

COMMUNICATIONS: CTAF/UNICOM 122.8

CLEARANCE DELIVERY PHONE: For CD ctc San Antonio Apch at 210-805-5516.

RADIO AIDS TO NAVIGATION: NOTAM FILE SAT.

SAN ANTONIO (VH) (H) VORTACW 116.8 SAT Chan 115 N29°38.64' W98°27.68' 357° 5.7 NM to fld. 1159/8E.

VOR unusable:

018°-022° byd 40 NM

028°-032° byd 40 NM

342°-347° byd 40 NM

355°-002° byd 40 NM blo 18,000'

**HORIZON** (74R) 9 S UTC-6(-5DT) N29°17.08' W98°29.90'

SAN ANTONIO

551 NOTAM FILE SJT

RWY 11-29: 2360X80 (TURF) 0.5% up W

RWY 11: Trees.

RWY 29: Trees.

RWY 16-34: 2250X100 (TURF) 1.0% up N

RWY 16: Trees.

RWY 34: Trees.

AIRPORT REMARKS: Unattended. Wild hogs on or invof arpt. No line of sight btn Rwy 34 and 29. Rwy 11-29 rough and uneven, not rglrly mntnd. Not suitable for acft.

AIRPORT MANAGER: 210-748-8672

COMMUNICATIONS: CTAF 122.9

CLEARANCE DELIVERY PHONE: For CD ctc San Antonio Apch at 210-805-5516.