

DARLINGTON CO (UDG)(KUDG) 9 N UTC-5(-4DT) N34°26.85' W79°53.19'

192 B NOTAM FILE UDG

RWY 05-23: H5500X100 (CONC) S-17, D-27 PCN 6 F/C/Y/T MIRL**RWY 05:** ODALS. REIL. PAPI(P2L)—GA 3.0° TCH 52'.**RWY 23:** REIL. PAPI(P2L)—GA 3.0° TCH 40'.**SERVICE:** FUEL 100LL, JET A LGT ODALS Rwy 05; MIRL Rwy 05-23; and twy lgts preset low instst dusk-0400Z†; to incr instst—CTAF. Aft 0400Z†, ACTVT ODALS Rwy 05; REIL Rwy 05 and 23; PAPI Rwy 05 and 23; MIRL Rwy 05-23; and twy lgts—CTAF.**AIRPORT REMARKS:** Attended Mon-Fri 1300-2200Z†. After hrs svc call 843-393-9928.**AIRPORT MANAGER:** 843-393-9928**WEATHER DATA SOURCES:** AWOS-3PT 119.925 (843) 393-8220.**COMMUNICATIONS:** CTAF/UNICOM 123.0

Ⓡ FLORENCE APP/DEP CON 118.6 (1130-0300Z†)

Ⓡ JACKSONVILLE CENTER APP/DEP CON 133.45 (0300-1130Z†)

CLNC DEL 118.55

CLEARANCE DELIVERY PHONE: For CD ctc Florence Apch at 843-665-0632, when Apch clsd ctc Jacksonville ARTCC at 904-845-1592.**RADIO AIDS TO NAVIGATION:** NOTAM FILE FLO.**FLORENCE (H) (H) VORTACW** 115.2 FLO Chan 99 N34°13.98' W79°39.43' 322° 17.2 NM to fld. 104/3W.

TACAN AZIMUTH unusable:

240°-285° byd 30 NM blo 4,000'

VOR unusable:

000°-017° byd 20 NM blo 7,000'

018°-037° byd 20 NM blo 10,000'

038°-051° byd 18 NM blo 5,000'

052°-074° byd 35 NM blo 10,000'

075°-116° byd 33 NM blo 4,000'

117°-142° byd 12 NM blo 10,000'

158°-170° byd 24 NM blo 10,000'

279°-301° byd 15 NM blo 10,000'

302°-342° byd 20 NM blo 10,000'

343°-359° byd 20 NM

DME unusable:


127°-173° byd 30 NM blo 3,000'

237°-302° byd 30 NM blo 4,000'

CHARLOTTE

H-9C, 12G, L-241, 25E, 36E

IAP

**DILLON CO** (DLC)(KDLC) 3 N UTC-5(-4DT) N34°26.94' W79°22.12'

133 B NOTAM FILE AND

RWY 07-25: H3000X60 (ASPH-AFSC) S-10 MIRL 0.5% up W**RWY 07:** Pole.**RWY 25:** Tree.**AIRPORT REMARKS:** Unattended.**AIRPORT MANAGER:** 843-845-8529**COMMUNICATIONS:** CTAF 122.9

FLORENCE APP/DEP CON 118.6 (1130-0300Z†)

JACKSONVILLE CENTER APP/DEP CON 133.45 (0300-1130Z†)

CLEARANCE DELIVERY PHONE: For CD ctc Florence Apch at 843-665-0632, when Apch clsd ctc Jacksonville ARTCC at 904-845-1592.**RADIO AIDS TO NAVIGATION:** NOTAM FILE FLO.**FLORENCE (H) (H) VORTACW** 115.2 FLO Chan 99 N34°13.98' W79°39.43' 051° 19.3 NM to fld. 104/3W.

TACAN AZIMUTH unusable:

240°-285° byd 30 NM blo 4,000'

VOR unusable:

000°-017° byd 20 NM blo 7,000'

018°-037° byd 20 NM blo 10,000'

038°-051° byd 18 NM blo 5,000'

052°-074° byd 35 NM blo 10,000'

075°-116° byd 33 NM blo 4,000'

117°-142° byd 12 NM blo 10,000'

158°-170° byd 24 NM blo 10,000'

279°-301° byd 15 NM blo 10,000'

302°-342° byd 20 NM blo 10,000'

343°-359° byd 20 NM

DME unusable:

127°-173° byd 30 NM blo 3,000'

237°-302° byd 30 NM blo 4,000'

CHARLOTTE

L-241, 35A, 36E

IAP

