

HUMACAO

DR HERMENEGILDO ORTIZ QUINONES (X63) 1 SE UTC-4 N18°08.28' W65°48.04' **PUERTO RICO-VIRGIN ISLANDS**
 35 B NOTAM FILE TJSJ
RWY 10-28: H2457X60 (ASPH) S-20 MIRL 0.4% up W
RWY 10: Tree.
AIRPORT REMARKS: Attended 1130-2000Z. Parachute Jumping. Birds activity on and in/ov arpt. Skydiving, ultralights opns on arpt. Rising terrain in/ov arpt. Cattle 500' from thld Rwy 28, occasionally on rwy. Loose stones and gravel on rwy and by. Ldg fee.
AIRPORT MANAGER: 787-852-8188
COMMUNICATIONS: CTAF 122.8
CLEARANCE DELIVERY PHONE: For CD ctc San Juan CERAP at 787-253-8664/8665
COMM/NAV/WEATHER REMARKS: Two-way radio communication required for acft and vehicles excp by prior request; Call 787-852-8188.

ISLA DE CULEBRA


BENJAMIN RIVERA NORIEGA (CPX)(TJCP) 1 N UTC-4 N18°18.78' W65°18.23' **PUERTO RICO-VIRGIN ISLANDS**
 43 B LRA NOTAM FILE TJSJ
RWY 13-31: H2596X60 (ASPH) S-12 MIRL 1.4% up NW
RWY 13: Hill.
RWY 31: Fence.
SERVICE: LGT Rtg bcn OTS indef. Rwy 13-31 MIRL-several lts OTS indef.
AIRPORT REMARKS: Unatndd SS-SR. Emergs only. Opns between SS-SR will be an own risk. Birds on and in/ov rwy. Rapidly rising terrain NW. Low alt maneuvering reqrd for final alignment to rwy, variable degrees of turbulence may be expd. Acft departing arpt northbound be alert for tfc descending on final for Charlotte Amalie St. Thomas, Cyril E. King (STT). Ldg Rwy 13 only (exc for adverse wx cond). Apch from NW thru Bahia Flamenco hdg 172°. Fly thru Laguna Del Flamenco until aprx parallel to highway in pass alter hdg to 153°, left turn to final. Rapidly rising terrain NW. Rwy, twy pavement cracking, loose stones. Ldg fee for all acft.
AIRPORT MANAGER: 787-742-0022
COMMUNICATIONS: CTAF 122.9
CLEARANCE DELIVERY PHONE: For CD ctc San Juan CERAP at 787-253-8664/8665

ISLA DE VIEQUES

ANTONIO RIVERA RODRIGUEZ (VQS)(TJVQ) 3 SW UTC-4 N18°08.09' W65°29.62' **PUERTO RICO-VIRGIN ISLANDS**
 48 B LRA NOTAM FILE TJSJ
RWY 09-27: H4294X75 (ASPH) S-20, D-40 MIRL 0.6% up W
RWY 09: PAPI(P4L)—GA 3.0° TCH 45'. Thld dspcd 200'. Trees.
RWY 27: Road. Rgt tfc.
RUNWAY DECLARED DISTANCE INFORMATION
RWY 09: TORA-4294 TODA-4294 ASDA-4294 LDA-4094
RWY 27: TORA-4294 TODA-4294 ASDA-4294 LDA-4094
SERVICE: LGT Rtg bcn OTS indef. Rwy 09 PAPI byd 9 degs R of RCL unusable.
AIRPORT REMARKS: Attended 1000-2200Z. VFR opns only. Rising terrain south. Acft not visible from opposite rwy end. Clsd to sked air carrier oper with more than 9 psgr seats and unsked air carrier oper with more than 30 psgr seats. PPR for other B-III acft and max wingspan of 88.75 ft, ctc AMGR. AMGR aftr hrs ph 787-439-5941. Const of twy south of Rwy 09-27. Rwy 09 day landing length 4094, night landing 3405. Rwy 09 dspcd thld marked at 207 ft. No thld lights. Ldg fee for all acft.

AIRPORT MANAGER: 787-729-8715
COMMUNICATIONS: CTAF/UNICOM 123.0
 (R) **SAN JUAN CERAP** 128.65
CLEARANCE DELIVERY PHONE: For CD ctc San Juan CERAP at 787-253-8664/8665

RADIO AIDS TO NAVIGATION: NOTAM FILE TIST.
ST THOMAS (L) (L) VOR/DME 108.6 STT Chan 23 N18°21.35' W65°01.47' 254° 29.9 NM to fld. 679/10W.
 VOR unusable:
 060°-070° byd 35 NM blo 2,200'
 085°-115° byd 16 NM blo 7,500'
 160°-175° byd 35 NM blo 2,500'
 255°-265° byd 25 NM
 290°-305° byd 15 NM
 DME unusable:
 085°-115° byd 30 NM blo 7,500'
COMM/NAV/WEATHER REMARKS: UNICOM monitored during attendance hrs.



L-5C, 6G, A-3G
 IAP