

**NEW COALINGA MUNI** (C80) 3 E UTC-8(-7DT) N36°09.73' W120°17.69'

**SAN FRANCISCO**

625 B NOTAM FILE RIU

H-4H, L-3C

**RWY 12-30:** H5000X100 (ASPH) S-30 MIRL 0.5% up NW

**RWY 12:** REIL. PAPI(P2L)—GA 3.0° TCH 40'.

**RWY 30:** REIL. PAPI(P2L)—GA 3.0° TCH 40'. Rgt tfc.

**RWY 01-19:** H2471X60 (ASPH-GRVL) S-12.5

**RWY 19:** Rgt tfc.

**SERVICE:** LGT REIL Rws 12 and 30; MIRL Rwy 12-30; Perimeter lgts H1 on dusk—0800Z†; after 0800Z† ACTVT—CTAF. PAPI Rws 12 and 30 opr consly. Rwy 30 VGSI OTS.

**AIRPORT REMARKS:** Attended irregularly. Rwy 01-19 clsd. Rwy 01-19 rwy sfc failed with potholes and brush.

**AIRPORT MANAGER:** 559-246-6243

**WEATHER DATA SOURCES:** AWOS-3 119.275 (559) 935-5960.

**COMMUNICATIONS:** CTAF/UNICOM 122.7

® **OAKLAND CENTER APP/DEP CON** 128.7

**CLEARANCE DELIVERY PHONE:** For CD ctc Oakland ARTCC at 510-745-3380.

**RADIO AIDS TO NAVIGATION:** NOTAM FILE PRB.

**PASO ROBLES (VL) (L) VORTACW** 114.3 PRB Chan 90 N35°40.35' W120°37.63' 013° 33.5 NM to fld. 817/16E.

TACAN AZIMUTH unusable:

120°-140° byd 27 NM blo 8,000'

DME unusable:

120°-140° byd 27 NM blo 8,000'

VOR unusable:

128°-138° byd 40 NM blo 6,000'


128°-138° byd 46 NM

139°-283° byd 40 NM

290°-295° byd 40 NM

325°-127° byd 40 NM

**COMM/NAV/WEATHER REMARKS:** AWOS OTS.



**HELIPAD H1:** H50X50 (ASPH) PERIMETER LGTS