

**REEDLEY MUNI** (O32) 4 N UTC-8(-7DT) N36°40.26' W119°27.06'

SAN FRANCISCO

386 B NOTAM FILE RIU

L-3C, 9A

**RWY 16-34:** H3300X60 (ASPH) S-12 MIRL

**RWY 16:** PAPI(P2L)—GA 3.0° TCH 41'.

**RWY 34:** PAPI(P2L)—GA 4.0° TCH 49'. Tree. Rgt tfc.

**SERVICE:** S4 FUEL 100LL, JET A LGT ACTIVATE PAPI Rwy 16 and 34; MIRL Rwy 16-34; twy lgts—CTAF.

**AIRPORT REMARKS:** Attended Mon-Fri 1600-2330Z†. Self svc fuel 24 hrs computerized credit card. For fuel phone number beside pumps, 7 days 1600-0100Z†.

**AIRPORT MANAGER:** 559-637-4203

**WEATHER DATA SOURCES:** AWOS-3PT 120.175 (559) 637-9453.

**COMMUNICATIONS:** CTAF/UNICOM 122.7


® **FRESNO APP/DEP CON** 132.35

**CLEARANCE DELIVERY PHONE:** For CD ctc Fresno Apch at 559-454-9805.

**RADIO AIDS TO NAVIGATION:** NOTAM FILE RIU.

**FRIANT (L) (L) VORTACW** 115.6 FRA Chan 103 N37°06.27'

W119°35.73' 148° 26.9 NM to fld. 2380/17E.



**REID-HILLVIEW OF SANTA CLARA CO** (See SAN JOSE on page 278)

**RIO LINDA** (L36) 1 S UTC-8(-7DT) N38°40.50' W121°26.73'

SAN FRANCISCO

46 TPA-846(800) NOTAM FILE RIU

**RWY 17-35:** H2625X42 (ASPH) S-12

**RWY 17:** Trees. Rgt tfc.

**RWY 35:** Trees.

**SERVICE:** S2 FUEL 100LL

**NOISE:** For noise abatement Rwy 17 right turn to heading 215° after t/kf to avoid overflight of school.

**AIRPORT REMARKS:** Attended 1600-0100Z†. Tree lines east, west and north of arpt—unlighted. Touch and go landings not authorized. Ultralights not authorized. Rwy 17-35 nstd cntrln spacing and width. Rwy 17-35 longl and lateral cracking.

The arpt is currently clsd to hgt ops.

**AIRPORT MANAGER:** 916-991-1725

**COMMUNICATIONS:** CTAF/UNICOM 123.0

**CLEARANCE DELIVERY PHONE:** For CD ctc NorCal Apch at 916-361-6874.