

ESPAÑOLA**OHKAY OWINGEH** (E14) 3 NE UTC-7(-6DT) N36°01.57' W106°02.72'**DENVER**
H-4L, 6F, L-8I

5760 B NOTAM FILE ABQ

RWY 16-34: H5007X75 (ASPH) S-18 PCN 7 F/D/Y/T MIRL 0.6% up N**RWY 16:** REIL. PAPI(P2L)—GA 3.0° TCH 40'.**RWY 34:** REIL. PAPI(P2L)—GA 3.0° TCH 40'.**RUNWAY DECLARED DISTANCE INFORMATION****RWY 16:** TORA-5007 TODA-5007 ASDA-5007 LDA-5007**RWY 34:** TORA-5007 TODA-5007 ASDA-5007 LDA-5007**SERVICE:** FUEL 100LL, JET A1+ LGT ACTVT REIL Rwy 16 and Rwy 34; PAPI Rwy 14 and Rwy 34; MIRL Rwy 16-34—CTAF.**AIRPORT REMARKS:** Unattended. 100LL fuel H24 with credit card. Wildlife on and invof arpt. Displ thld on Rwy 16. Rwy 16 displ threshold removed. Main gate locked at all times. Airport access gate combination - 4751#. 7083 ft MSL twr 3.3 NM 010 degs N of arpt.**AIRPORT MANAGER:** 505-692-3345**COMMUNICATIONS:** CTAF 122.9**CLEARANCE DELIVERY PHONE:** For CD ctc: Albuquerque ARTCC at 505-856-4861.**RADIO AIDS TO NAVIGATION:** NOTAM FILE SAF.**SANTA FE (L) VORTACW** 110.6 SAF Chan 43 N35°32.43' W106°03.90' 349° 29.1 NM to fld. 6268/13E.

VORTAC unusable:

015°-030° byd 30 NM blo 14,600'

ESTANCIA MUNI (E92) 1 E UTC-7(-6DT) N34°45.80' W106°02.48'**ALBUQUERQUE**

6100 NOTAM FILE ABQ

RWY 08-26: 4000X50 (GRVL)**RWY 26:** Brush.**AIRPORT REMARKS:** Unattended. Cattle and birds on and invof rwy. Rwy 08-26 soft when wet +2-3 ft brush in prim sft 50-70 ft fm cntrln both sides. Rwy 08 -1 ft culvert in prim sfc 200 ft fm thr 70 ft r of cntrln. +12 ft tree 134 ft fm thr 78 ft r of cntrln. Rwy 26 +3-5 ft brush 0-200 ft fm thr 125 ft l and r of cntrln.**AIRPORT MANAGER:** 505-401-3701**COMMUNICATIONS:** CTAF 122.9**CLEARANCE DELIVERY PHONE:** For CD ctc: Albuquerque ARTCC at 505-856-4861.