
COLUMBIA (4G8) 1 WNW UTC-5(-4DT) N41°19.12' W81°57.63'

DETROIT

811 NOTAM FILE CLE

L-30G

RWY 18-36: H3152X40 (ASPH) LIRL(NSTD)**RWY 18:** Thld dsplcd 300'. Trees.**RWY 36:** Thld dsplcd 209'. Tree.**SERVICE:** LGT NSTD LIRL Rwy 18-36 OTS indefly. Rwy 18-36 NSTD LIRL due to misg thr lgts.**AIRPORT REMARKS:** Attended Mon-Fri 1400-2200Z; Sat-Sun irreg. Unatn'd major hols. Rwy 18-36 clsd dly SS-SR. Occl deer, birds, & otr wildlife on & invof arpt. Rwy end 18: nstd nrs only due to no dthr mkgs, no arrowheads; north 300 ft unmkd. Rwy end 36: nstd nrs only due to no dthr mkgs, no arrowheads; north 300 ft unmkd.**AIRPORT MANAGER:** 757-510-6788**COMMUNICATIONS:** CTAF/UNICOM 122.8**CLEARANCE DELIVERY PHONE:** For CD etc Cleveland Apch at 216-352-2323.**RADIO AIDS TO NAVIGATION:** NOTAM FILE CLE.**DRYER (VH) (DH) VOR/DME** 113.6 DJB Chan 83 N41°21.48' W82°09.72' 109° 9.4 NM to fld. 780/5W.

VOR unusable:

001°-010° byd 40 NM

020°-024° byd 40 NM

080°-095° byd 40 NM

110°-120° byd 40 NM

135°-150°

155°-165°

185°-197°

210°-218°

219°-224° byd 40 NM

225°-235° byd 40 NM blo 11,000'

225°-235° byd 95 NM

225°-245° byd 20 NM blo 3,500'

246°-257° byd 40 NM

286°-355° byd 40 NM

DME unusable:

187°-197°

289°-310°

322°-332°

350°-060°

COLUMBIANA CO (See EAST LIVERPOOL on page 282)
