

MEDINA MUNI (1G5) 4 E UTC-5(-4DT) N41°07.89' W81°45.89' DETROIT
 1190 B NOTAM FILE CLE L-30G
RWY 09-27: H3556X75 (ASPH) S-30 MIRL 0.4% up E IAP
RWY 09: PAPI(P4L)—GA 3.0° TCH 25'. Tree.
RWY 27: REIL. PAPI(P4L)—GA 3.5° TCH 30'.
RWY 01-19: H2868X60 (ASPH) S-25 MIRL 0.7% up N
RWY 01: PAPI(P4L)—GA 3.0° TCH 25'. P-line.
RWY 19: PAPI(P4L)—GA 4.0° TCH 34'. Thld dsplcd 737'. Trees.
SERVICE: S4 FUEL 100LL, JET A+ LGT ACTIVATE REIL Rwy 27; PAPI Rwy 01, 19 and Rwy 27; MIRL Rwy 01-19 and Rwy 09-27—CTAF. PAPI Rwy 01, 19 and Rwy 27 opr constly Dusk-0300Z†. Rwy 09 PAPI OTS indef.
NOISE: Noise-sensitive residential and livestock area invof all rwy ends. Maintain rwy hdg til reaching TPA.
AIRPORT REMARKS: Attended 1300-0100Z† Apr-Oct, 1300-2200Z† Nov-Mar. Deer, birds and other wildlife on and invof arpt.
 Fuel avbl 24 hr self ser.
AIRPORT MANAGER: 330-239-1606
COMMUNICATIONS: CTAF/UNICOM 123.0
 ® **CLEVELAND APP/DEP CON** 125.35
CLEARANCE DELIVERY PHONE: For CD ctc Cleveland Apch at 216-352-2323.
RADIO AIDS TO NAVIGATION: NOTAM FILE CLE.
DRYER (VH) (DH) VOR/DME 113.6 DJB Chan 83 N41°21.48' W82°09.72' 132° 22.5 NM to fld. 780/5W.
 VOR unusable:
 001°-010° byd 40 NM
 020°-024° byd 40 NM
 080°-095° byd 40 NM
 110°-120° byd 40 NM
 135°-150°
 155°-165°
 185°-197°
 210°-218°
 219°-224° byd 40 NM
 225°-235° byd 40 NM blo 11,000'
 225°-235° byd 95 NM
 225°-245° byd 20 NM blo 3,500'
 246°-257° byd 40 NM
 286°-355° byd 40 NM
 DME unusable:
 187°-197°
 289°-310°
 322°-332°
 350°-060°

MIAMI UNIVERSITY (See OXFORD on page 303)

MIDDLE BASS ISLAND

MIDDLE BASS ISLAND (3T7) 1 NE UTC-5(-4DT) N41°41.30' W82°48.49' DETROIT
 579 NOTAM FILE CLE
RWY 10-28: H1852X75 (ASPH)
RWY 10: Thld dsplcd 52'. Tree. Rgt tfc.
RWY 28: Tree.
AIRPORT REMARKS: Unattended. Acft ops prohibited dusk-dawn. All tfc pats rmn south of arpt. No TGL; no student trg. Helipad on south side of rwy is rstd to EMS helicopters only. Lndg fee: prkg/ramp fees for all pvt and coml acft.
AIRPORT MANAGER: 419-285-3371
COMMUNICATIONS: CTAF/UNICOM 122.8
CLEARANCE DELIVERY PHONE: For CD ctc Cleveland Apch at 216-352-2323.

MIDDLE BASS-EAST POINT (3W9) 1 NE UTC-5(-4DT) N41°41.67' W82°47.79' DETROIT
 582 NOTAM FILE CLE
RWY 09-27: 2085X67 (TURF)
RWY 09: Berm.
RWY 27: Road. Rgt tfc.
AIRPORT REMARKS: Attended May-Oct ired, unatndd Nov-Apr. Ocnl deer, birds and otr wildlife on and invof arpt. Rwy 09-27 soft and wet in spring. Nmrs trees and bldgs in close proximity to rwy. Exp sgfnt ws and turb on apch and dep when wind exceeds 10 kt. For wind indir use segmented crc at 3T7 arpt.
AIRPORT MANAGER: 216-870-6513
COMMUNICATIONS: CTAF 122.8
CLEARANCE DELIVERY PHONE: For CD ctc Cleveland Apch at 216-352-2323.

MIDDLE BASS-EAST POINT (See MIDDLE BASS ISLAND on page 296)