

AUGUSTA**AUGUSTA SPB** (M00) 3 S UTC-5(-4DT) N44°16.05' W69°46.90'**MONTREAL**

23 NOTAM FILE BGR

WATERWAY 13W-31W: 2500X100 (WATER)**WATERWAY 13W:** Trees. Rgt tfc.**WATERWAY 31W:** Trees.**SEAPLANE REMARKS:** Unattended. Daytime use only. Unmarked shoals E of sealane. Location has tidal fluctuation of 4'. Sealane poorly marked, irregular shaped channel. Docks removed durg winter months Oct-May.**AIRPORT MANAGER:** 207-626-2306**COMMUNICATIONS: CTAF** 122.9**CLEARANCE DELIVERY PHONE:** For CD ctc Portland Apch at 207-874-7320, when Apch clsd ctc Boston ARTCC at 603-879-6859.**AUGUSTA STATE** (AUG)(KAUG) 1 NW UTC-5(-4DT) N44°19.24' W69°47.84'**MONTREAL**

352 B TPA—1400(1048) NOTAM FILE AUG

H-11D, L-32H**RWY 17-35:** H5002X100 (ASPH-GRVD) S-50, D-60 HIRL 0.7% up S**IAP, AD****RWY 17:** MALSR. PAPI(P4L)—GA 3.0° TCH 53'. Tree.**RWY 35:** REIL. PAPI(P4L)—GA 3.0° TCH 40'. Tree.**RWY 08-26:** H2613X75 (ASPH) S-30 MIRL**RWY 08:** Trees.**RWY 26:** Fence.**RUNWAY DECLARED DISTANCE INFORMATION****RWY 08:** TORA-2613 TODA-2613 ASDA-2613 LDA-2613**RWY 17:** TORA-5002 TODA-5002 ASDA-5002 LDA-5002**RWY 26:** TORA-2613 TODA-2613 ASDA-2613 LDA-2613**RWY 35:** TORA-5002 TODA-5002 ASDA-5002 LDA-5002**ARRESTING GEAR/SYSTEM****RWY 17:** EMAS**RWY 35:** EMAS**SERVICE:** S4 **FUEL** 100LL, JET A **LGT ACTVT** MALSR Rwy 17, REIL Rwy 35, PAPI Rwy 17 and Rwy 35, HIRL Rwy 17-35, MIRL Rwy 08-26—CTAF.**AIRPORT REMARKS:** Attended 1200-0100Z†. Arpt unatndd aft dark durg snow and ice season. Birds and deer on and invof arpt. Seagulls on and invof rwy intersections. Pilots conducting EFVS ops; be aware LED ALS in use Rwy 17. Fld cond rprts snow depths, BA may not be avbl for rwys fm 2300-1100Z†. For 100LL aft nml bus hrs call 207-622-2507. Rwy 35 designated calm wind rwy. Rwy 17-35 have EMAS category B2. Twy F east clsd to all acft with wing span greater than 45'. Air carrier ramp clsd to general aviation tfc. Ldg fee for multi-engine acft, fee waived with fuel purchase.**AIRPORT MANAGER:** 207-626-2306**WEATHER DATA SOURCES:** ASOS 118.325 (207) 623-0432.**COMMUNICATIONS:** CTAF/UNICOM 123.0**RCO** 122.1R 114.95T 122.2 (BANGOR RADIO)® **PORTLAND APP/DEP CON** 128.35 (1045-0500Z†)® **BOSTON CENTER APP/DEP CON** 128.2 (112°-292°) 120.25 (293°-111°) (0500-1045Z†)**CLNC DEL** 119.95 299.2**CLEARANCE DELIVERY PHONE:** For CD when Portland Apch clsd, ctc Boston ARTCC at 603-879-6859.**CONTINUED ON NEXT PAGE**

CONTINUED FROM PRECEDING PAGE

AIRSPACE: CLASS E.

RADIO AIDS TO NAVIGATION: NOTAM FILE AUG.

(VL) (DH) VOR/DME 114.95 AUG Chan 96(Y) N44°19.20' W69°47.79' at fld. 349/18W.

VOR unusable:

005°-015° byd 10 NM blo 7,000'
 018°-050° byd 40 NM
 055°-058° byd 40 NM
 065°-089° byd 40 NM
 075°-089° byd 25 NM blo 3,000'
 090°-115° byd 15 NM
 116°-175° byd 40 NM
 116°-189° byd 25 NM blo 3,000'
 188°-207° byd 40 NM
 190°-205° byd 10 NM blo 5,000'
 206°-220° byd 25 NM blo 3,000'
 208°-213° byd 40 NM blo 3,000'
 208°-213° byd 49 NM blo 7,000'
 208°-213° byd 68 NM
 225°-245° byd 40 NM
 246°-256° byd 40 NM blo 7,000'
 246°-256° byd 53 NM
 257°-261° byd 40 NM
 271°-275° byd 40 NM
 300°-353° byd 40 NM

DME unusable:

010°-070° byd 25 NM blo 7,000'
 071°-143° byd 25 NM blo 3,000'
 144°-154° byd 25 NM blo 7,000'
 155°-189° byd 25 NM blo 3,000'
 190°-205° byd 10 NM blo 5,000'
 206°-220° byd 25 NM blo 3,000'
 221°-285° byd 15 NM blo 6,000'

DUNNS NDB (LOMW) 366 AU N44°24.66' W69°51.64' 171° 6.1 NM to fld. 238/18W.

ILS 108.7 I-AUG Rwy 17. Class IB. LOM DUNNS NDB. Glideslope unusable byd 5° right side of LOC course; blw 430'; byd 9 NM. LOC unusable fm 0.5 NM to thld abv 1,500'. Autopilot cpd apch NA blw 570' MSL.

BANGOR

BANGOR INTL (BGR)(KBGR) P (ANG ARNG) 3 W UTC-5(-4DT) N44°48.45' W68°49.69'

192 B TPA—See Remarks LRA ARFF Index—See Remarks NOTAM FILE BGR

RWY 15-33: H11440X200 (ASPH-GRVD) S-100, D-210, 2D-400 PCR 735 R/B/W/U HIRL CL

RWY 15: ALSF2. TDZL. PAPI(P4L)—GA 3.0° TCH 55'. RVR-TMR 0.4% down.

RWY 33: MALSR. TDZL. PAPI(P4L)—GA 3.0° TCH 57'. RVR-TMR Trees.

RUNWAY DECLARED DISTANCE INFORMATION

RWY 15: TORA-11440 TODA-11440 ASDA-11440 LDA-11440

RWY 33: TORA-11440 TODA-11440 ASDA-11440 LDA-11440

SERVICE: S4 FUEL 100LL, JET A OX 2, 4 MILITARY—JASU 1(MD-3) 1(MC-11) (MA-1A) FUEL A++ (Mil), A, A+
 (C207-992-4600) (NC-100LL) FLUID SP PRESAIR LPOX LOX -Off-base contracted LOX avbl H24-rqr 24 hr notice. OIL
 O-133-148(Mil)

AIRPORT REMARKS: Attended continuously. TPA for turbo jet acft is 2000(1808) unless otherwise instructed. ARFF Index B
 with Index E capabilities avbl 24/7. Flight Notification Service (ADCUS) available.

MILITARY REMARKS: Transient acft may be diverted to civilian side during non-duty hrs & weekends. Fee required; no ANG
 transient alert. CAUTION Bash Phase II period Sep-Nov, Apr-May. Expect increased bird activity. Ctc Base Ops/Command
 Post/SOF for current bird watching cond. MISC Rwy 15-33 grooved. ANG Opr 1100-1930Z‡ Mon-Fri, clsd weekends and
 hol. PPR rqr for ANG ramp. Ctc afd mgmt DSN 698-7232, C207-404-7232 for PPR dur opr hrs. Pre-coord all
 transportation requirements and haz cargo with PPR rqr. PPR valid +/- 1 hr unless prior coord. 3 hr out call, 30 min
 out call 311.0 to CFM customs/AG and tran svc. Comd post C207-404-7788 24 hrs. ARNG Opr 1230-2100Z‡ Mon-Fri
 exc hol. Ltd maint. J8. PPR May-Oct svc DSN 626-1100.

AIRPORT MANAGER: 207-992-4600

WEATHER DATA SOURCES: ASOS 127.75 (207) 561-2515.

COMMUNICATIONS: ATIS 127.75 (207-561-2524) UNICOM 122.95

RCO 122.2 (BANGOR RADIO)

® APP/DEP CON 118.925 124.5

TOWER 120.7 GND CON 121.9 CLNC DEL 135.9

AIRSPACE: CLASS C svc ctc APP CON.

CONTINUED ON NEXT PAGE